

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8708100356 DOC. DATE: 87/08/05 NOTARIZED: NO DOCKET #
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316
 AUTH. NAME AUTHORITY AFFILIATION
 SMITH, W. G. Indiana & Michigan Electric Co.
 RECIP. NAME RECIPIENT AFFILIATION
 DAVIS, A. B. NRC - No Detailed Affiliation Given

SUBJECT: Followup RO re portion of north outside fire protection ring
 header that had been isolated due to leaking fire hydrant,
 per 870803 rept. Leak due to potable water supply piping.
 Header returned to svc on 870804.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD3-3 LA	1	PD3-3 PD	1
	WIGGINGTON, D	1		
INTERNAL:	ACRS MICHELSON	1	ACRS MOELLER	2
	AEOD/DOA	1	AEOD/DSP/NAS	1
	AEOD/DSP/ROAB	2	AEOD/DSP/TPAB	1
	DEDRO	1	NRR/DEST/ADE	1
	NRR/DEST/ADS	1	NRR/DEST/CEB	1
	NRR/DEST/ELB	1	NRR/DEST/ICSB	1
	NRR/DEST/MEB	1	NRR/DEST/MTB	1
	NRR/DEST/PSB	1	NRR/DEST/RSB	1
	NRR/DEST/SGB	1	NRR/DLPQ/HFB	1
	NRR/DLPQ/GAB	1	NRR/DOEA/EAB	1
	NRR/DREP/RAB	1	NRR/DREP/RPB	2
	NRR/PMAS/ILRB	1	REG FILE 02	1
	RES DEPY GI	1	RES TELFORD, J	1
	RES/DE/EIB	1	RGN3 FILE 01	1
EXTERNAL:	EG&G GROH, M	5	H ST LOBBY WARD	1
	LPDR	1	NRC PDR	1
	NSIC HARRIS, J	1	NSIC MAYS, G	1

TOTAL NUMBER OF COPIES REQUIRED: LTTR 44 ENCL 2



INDIANA & MICHIGAN ELECTRIC COMPANY

Donald C. Cook Nuclear Plant
P.O. Box 458, Bridgman, Michigan 49106

August 5, 1987

Donald C. Cook Nuclear Plant Unit Nos. 1 and 2
Docket Nos. 50-315 and 50-316
License Nos. DPR-58 and DPR-74


U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Attn: A. B. Davis

Dear Mr. Davis:

On August 3, 1987, we informed your office through telephone and written followup reports that a portion of the north outside fire protection ring header had been isolated due to what appeared to be a leaking fire hydrant. Upon further investigation, it was determined that the leak was, in fact, in the potable water supply piping that runs immediately adjacent to the fire protection piping in this area. The fire protection ring header was returned to service at 1218 hours on August 4, 1987.

Respectfully,


W.G. Smith, Jr.

/bab

cc: See Attached Distribution

8708100356 870805
PDR ADOCK 05000316
S PDR

IK22
1/0

A. B. Davis, Region III
R. C. Callen, MPSC
D. Hahn, MDPH
G. Charnoff, Esq.
Dottie Sherman, ANI Library
D. L. Wigginton, NRC
Records Center, INPO
J. E. Dolan
M. P. Alexich
R. F. Kroeger
H. B. Brugger
R. W. Jurgensen
NRC Resident Inspector
PNSRC
A. A. Blind
J. G. Feinstein/B. P. Lauzau
File