

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	C	C	2	2	0	0	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4			5	
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE				30	57	CAT	58

CON'T

7 8 60 61 68 69 74 75 80
 REPORT SOURCE L 6 0 5 0 0 0 3 1 6 7 0 9 3 0 7 9 8 1 0 1 7 7 9 9
 DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | DURING THE PERFORMANCE OF STEAM GENERATOR STOP VALVE DUMP VALVE

03 TESTING, MRV 232 (NUMBER 3 STEAM GENERATOR STOP VALVE DUMP VALVE)

04 | FAILED TO OPEN. THIS CONDITION WAS NON CONSERVATIVE WITH RESPECT

05 | TO T.S. 3.3.2.1 TABLE 3.3-3 ITEM 4b.

0	6	
---	---	--

0	7	
---	---	--

0 8 | _____ 8

0 9		SYSTEM CODE C D		11	CAUSE CODE E		12	CAUSE SUBCODE A		13	COMPONENT CODE V A L V O P					14	COMP. SUBCODE F		15	VALVE SUBCODE Z		16																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																					
7	8	9	10		11		12	13							14			15			16																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																						
17		LER/RO REPORT NUMBER		EVENT YEAR 7 9		21	22	SEQUENTIAL REPORT NO. 0 3 3		24	25	26	OCCURRENCE CODE 0 3		28	29	REPORT TYPE L		30	31	REVISION NO. 0		32																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
ACTION TAKEN A		FUTURE ACTION Z		EFFECT ON PLANT Z		33	34	SHUTDOWN METHOD Z		35	36	HOURS 0 0 0		37	38	39	ATTACHMENT SUBMITTED N		40	41	NPRD-4 FORM SUB. Y		42	43	PRIME COMP. SUPPLIER X		44	45	46	47	COMPONENT MANUFACTURER A 4 9 9		26																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																										
18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80		81		82		83		84		85		86		87		88		89		90		91		92		93		94		95		96		97		98		99		100		101		102		103		104		105		106		107		108		109		110		111		112		113		114		115		116		117		118		119		120		121		122		123		124		125		126		127		128		129		130		131		132		133		134		135		136		137		138		139		140		141		142		143		144		145		146		147		148		149		150		151		152		153		154		155		156		157		158		159		160		161		162		163		164		165		166		167		168		169		170		171		172		173		174		175		176		177		178		179		180		181		182		183		184		185		186		187		188		189		190		191		192		193		194		195		196		197		198		199		200		201		202		203		204		205		206		207		208		209		210		211		212		213		214		215		216		217		218		219		220		221		222		223		224		225		226		227		228		229		230		231		232		233		234		235		236		237		238		239		240		241		242		243		244		245		246		247		248		249		250		251		252		253		254		255		256		257		258		259		260		261		262		263		264		265		266		267		268		269		270		271		272		273		274		275		276		277		278		279		280		281		282		283		284		285		286		287		288		289		290		291		292		293		294		295	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 THE COIL FOR SOLENOID VALVE XSO 232 WAS FOUND TO BE OPEN. THE

111 | COIL WAS REPLACED AND THE PROPER OPERATION OF MRV-232 WAS VERIFIED.

1 2 THE ACTION REQUIREMENT OF T.S. TABLE 3.3-3, ITEM 13 WAS FULFILLED.

1 2 COIL MANUFACTURER ASCO PART NO. 98-824-8D 240 VOLT DC COIL.

1	4	
---	---	--

8 9
FACILITY STATUS (28) 1 5 E 0 5 2 (29) 0 5 2 (29) NA (30) 30
METHOD OF DISCOVERY (31) B (31) 45 46 SURVEILLANCE TESTS (32) 47 48 49 50

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 Z 33 34

AMOUNT OF ACTIVITY (35)

NA

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPOSURES										
NUMBER				TYPE	DESCRIPTION					
1	7	0	0	0	(37) Z	(38) NA				

		PERSONNEL INJURIES		
NUMBER		DESCRIPTION		(41)
1	8	0	0	(40) NA

7910220275

LOSS OF OR DAMAGE TO FACILITY		(43)
TYPE	DESCRIPTION	

[illegible]

PUBLICITY *										NRC USE ONLY									
ISSUED		DESCRIPTION																	
2	0	N	(44)	NA															
7	8	9	10	68															
				69															
				80															

NAME OF PREPARER S. DeLong

PHONE: 616-465-5901

