

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

REPORT SOURCE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

7 8

0	9
---	---

NO.
0

COMPONENT
MANUFACTURER
W | 1 | 2 | 0

7 8

7. 6

7 6

7 8

7 **8**

7
8

7, 8

PHONE: ^{88 89} (616) 465-5901 X-316

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS:

AND RETURNED TO SERVICE. A CHECK OF THE MALFUNCTION ALARM REVEALED THAT IT WAS NOT DESIGNED TO ACTIVATE UNDER THE EXISTING CONDITION. ALL OPERATORS HAVE BEEN REINSTRUCTED TO MONITOR THE APDMS PRINTOUTS CLOSELY TO INSURE THAT ALL SURVEILLANCE REQUIREMENTS ARE MET SHOULD THE APDMS FAIL TO FUNCTION.

10-10-54

10-10-54

10-10-54 10-10-54 10-10-54 10-10-54 10-10-54