

CENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	C	C	1	2	0	0	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4			5	
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE				30	57	CAT	58

CON'T

0	1	REPORT SOURCE	L	6	0	5	0	0	0	3	1	5	7	1	0	0	1	7	9	8	1	0	3	0	7	9	9	
7	8	60	61	DOCKET NUMBER										68	69	EVENT DATE					74	75	REPORT DATE					80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | DURING THE INVESTIGATION OF A HIGH LEVEL INDICATION FOR NUMBER

0 3 | FOUR (4) STEAM GENERATOR, TRANSMITTER BLP-142 WAS FOUND TO HAVE

0 4 | DRIFTED 7 PER CENT HIGH. THIS CONDITION WAS NON CONSERVATIVE

0 5 | WITH RESPECT TO T.S. TABLE 3.3-1 ITEMS 14 AND 15.

0 6 |

0 7 |

0 8 |

7 8 9 80

0 9		SYSTEM CODE I A		11	CAUSE CODE E		12	CAUSE SUBCODE E		13	COMPONENT CODE I N S T R U					14	COMP. SUBCODE T		15	VALVE SUBCODE Z		16	
7	8	9	10		11		12		13					18		19		20					
17		LER/RO REPORT NUMBER		EVENT YEAR 7 9		21	22	SEQUENTIAL REPORT NO. 0 5 2		24	26	OCCURRENCE CODE /		27	REPORT TYPE 0 3		28	29	REVISION NO. L		30	31	
ACTION TAKEN E		18	FUTURE ACTION X		19	EFFECT ON PLANT Z		20	SHUTDOWN METHOD Z		21	HOURS 0 0 0 0		22	ATTACHMENT SUBMITTED Y		23	NPRD-4 FORM SUB. Y		24	PRIME COMP. SUPPLIER A		25
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	COMPONENT MANUFACTURER B 0 8 0		26						

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 THE TRANSMITTER, BLP-142, WAS RECALIBRATED TO THE PROPER SPECIFICATION
1 1 AND THEN PLACED BACK IN OPERATION. THE TRANSMITTER HAS SHOWN NO
1 2 DRIFTING SINCE THE INITIAL SHIFT. THIS PROBLEM HAS BEEN BROUGHT
1 3 TO THE ATTENTION OF THE MANUFACTURER AND WE ARE WAITING FOR A
1 4 REPLY FROM THEM. SEE SUPPLEMENT.

8 9
FACILITY STATUS (28) 1 5 E 9 10 % POWER 1 0 0 12 13 OTHER STATUS (30) NA 44
7 8 9 10 11 12 13 14
ACTIVITY CONTENT
RELEASED OF RELEASE (33) 1 6 Z 9 10 11 12 13 AMOUNT OF ACTIVITY (35) NA 44
7 8 9 10 11 12 13 14
PERSONNEL EXPOSURES
NUMBER (37) 1 7 0 9 10 11 12 13 TYPE (38) Z DESCRIPTION (39) NA 44
7 8 9 10 11 12 13 14
PERSONNEL INJURIES
NUMBER (40) 1 8 0 9 10 11 12 13 DESCRIPTION (41) NA 44
7 8 9 10 11 12 13 14
LOSS OF OR DAMAGE TO FACILITY
TYPE (42) 1 9 Z 9 10 11 12 13 DESCRIPTION (43) NA 44
7 8 9 10 11 12 13 14
PUBLICITY
ISSUED (44) 2 0 N 9 10 11 12 13 DESCRIPTION (45) NA 44
7 8 9 10 11 12 13 14
METHOD OF DISCOVERY (31) A 45 46 OPERATOR OBSERVATION (32) 80
DISCOVERY DESCRIPTION (32) 80
LOCATION OF RELEASE (36) NA 45 80
7911070488
NRC USE ONLY
68 69 80

NAME OF PREPARER S. D. DeLong

PHONE: 616-465-5901

SUPPLEMENT TO LER #79-052/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

THIS INVESTIGATION WILL REMAIN OPEN AND IF A DEFINITE CAUSE
IS DETERMINED A SUPPLEMENTAL LER WILL BE SUBMITTED.
THE ACTION ITEM REQUIREMENT OF TABLE 3.3-1 FOR ITEMS 14
AND 15 WAS FULFILLED.