

CONTROL BLOCK: | | | | | | | ① (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	1	6	7	1	1	1	6	7	9	8	1	2	0	7	7	9	9
60	61	DOCKET NUMBER					68	69	EVENT DATE					74	REPORT DATE					80				

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 8 | _____ 8

0 9		SYSTEM CODE X X		CAUSE CODE E		CAUSE SUBCODE X		COMPONENT CODE X X X X X				COMP. SUBCODE Z		VALVE SUBCODE Z	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
LER/RO REPORT NUMBER		EVENT YEAR 7 9		SEQUENTIAL REPORT NO. 0 6 0		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0		ACTION TAKEN X		FUTURE ACTION F	
23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38
SHUTDOWN METHOD Z		EFFECT ON PLANT Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED N		NPRD-4 FORM SUB. N		PRIME COMP. SUPPLIER N		COMPONENT MANUFACTURER W 1 2 0		29	
39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | AN AIR HANDLING UNIT DRAIN LINE WAS FOUND PLUGGED. THIS RESULTED IN THE

1 1 | OVERFLOW OF DRAINAGE FROM THE UNIT DURING DEFROST AND ICE FORMATION AROUND

1 2 | THE DOORS. THE ICE WAS REMOVED AND THE DRAIN LINE WAS CLEARED.

1 3 | A MODIFICATION HAS BEEN INITIATED TO CORRECT PROBLEMS ASSOCIATED WITH

1 4 | AIR HANDLING UNIT DEFROSTING.

8 9 FACILITY STATUS (28) 1 5 E 1 0 0 % POWER (29) NA OTHER STATUS (30) METHOD OF DISCOVERY (31) B ROUTINE TOUR DISCOVERY DESCRIPTION (32)

7 8 9 ACTIVITY CONTENT 10 11 12 13 44 45 46 80

1 6 Z (33) Z (34) NA AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

7 8 9 10 11 44 45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	NA	(39)

PERSONNEL INJURIES		DESCRIPTION	
NUMBER	DESCRIPTION		
1 8	0 0 0 (40) NA		

7		8		9		11		12	
TYPE		DESCRIPTION							
43		LOSS OF OR DAMAGE TO FACILITY							
7		11		NA					

7912130380

1	9	2	42	NA
7	8	9	10	
PUBLICATION			NRC USE ONLY	
ISSUED		DESCRIPTION		45

[illegible]

NAME OF PREPARER M.S. BROWN

PHONE: 616-465-5901, EXT. 398