

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9005310145 DOC. DATE: 90/05/24 NOTARIZED: YES DOCKET #
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316
 AUTH. NAME AUTHOR AFFILIATION
 ALEXICH, M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Responds to NRC Bulletin 90-001, "Loss of Fill Oil in Transmitters Mfg by Rosemount."

DISTRIBUTION CODE: A013D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 3
 TITLE: Generic Ltr 90-01 re NRC Regulatory Impact Survey

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD3-1 LA	1 1	PD3-1 PD	1 1
	GIITTER, J.	1 1		
INTERNAL:	J. PARTLOW	1 1	NRR/DET/ECMB 9H	1 1
	NRR/DOEA/OTSB11	1 1	NRR/DST 8E2	1 1
	NRR/DST/SELB 8D	1 1	NRR/DST/SICB 7E	1 1
	NRR/DST/SRXB 8E	1 1	OC/LEMB	1 0
	OGC/HDS1	1 0	REG FILE 01	1 1
	RES/DSIR/EIB	1 1	STEPHEN SANDS	1 1
	TOM BOYCE	1 1		
EXTERNAL:	LPDR	1 1	NRC PDR	1 1
	NSIC	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 19 ENCL 17 0



AEP:NRG:1109

Donald C. Cook Nuclear Plant Units 1 & 2
Docket Nos. 50-315 and 50-316
License Nos. DPR-58 and DPR-74
BULLETIN 90-01: LOSS OF FILL-OIL IN TRANSMITTERS
MANUFACTURED BY ROSEMOUNT

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555

Attn: T. E. Murley

May 24, 1990

Dear Dr. Murley:

The following information is provided in response to NRC Bulletin 90-01. Bulletin 90-01 requires licensees with particular models of Rosemount pressure and differential pressure transmitters to identify and replace those transmitters that are installed in certain safety-related systems. Evidently, a number of these transmitters have exhibited a gradual and difficult to detect calibration shift due to the loss of fill oil from the sensor module.

There are no Rosemount Model 1153 Series B, 1153 Series D or Model 1154 transmitters installed at Cook Nuclear Plant. These are the models identified in the bulletin as being potentially defective. While we do have some Model 1151 Rosemount transmitters, these were purchased as commercial grade units and are installed in non-safety related systems.

This letter is submitted pursuant to 10CFR50.54(f) and, as such, an oath statement is enclosed.

Sincerely,

M. P. Alexich
Vice President

9005310145 900524
PDR ADOCK 05000315
Q PDC

19013
110

Dr. T. E. Murley

-2-

AEP:NRC:1109

MPA/dfw

cc: D. H. Williams, Jr.
A. A. Blind - Bridgman
J. P. Padgett
G. Charnoff
A. B. Davis - Region III
NRC Resident Inspector - Bridgman
NFEM Section Chief

STATE OF OHIO)
COUNTY OF FRANKLIN)

Milton P. Alexich, being duly sworn, deposes and says that he is the Vice President of licensee Indiana Michigan Power Company, that he has read the foregoing response to Bulletin 90-01: Loss of Fill-Oil In Transmitters Manufactured By Rosemount and knows the contents thereof; and that said contents are true to the best of his knowledge and belief.

M. Alexich

Subscribed and sworn to before me
this 23rd day of May, 1990.

Rita D. Hill
NOTARY PUBLIC

RITA D. HILL
NOTARY PUBLIC, STATE OF OHIO
MY COMMISSION EXPIRES 6-28-94

