

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9407060158 DOC.DATE: 94/06/28 NOTARIZED: NO DOCKET #
 FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315
 AUTH.NAME AUTHOR AFFILIATION
 FITZPATRICK,E. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele
 RECIP.NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Advises that steam generator tube R8C35 was removed from
 svc during unit 1 cycle 13-14 refueling outage &
 administrative controls have been established.

DISTRIBUTION CODE: IE13D COPIES RECEIVED:LTR 1 ENCL 0 SIZE: 2
 TITLE: Bulletin Response, 88-02 Rapidly Propagating Fatigue Cracks in Steam

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID	CODE/NAME	LTR	ENCL		ID	CODE/NAME	LTR	ENCL
	PD3-1	PD	1	1		HICKMAN,J	1	1	
INTERNAL:	AEOD/DSP/ROAB		1	1		NRR/DRPW/OGCB	1	1	
	NRR/DSSA		1	1		NRR/EMCB	1	1	
	NRR/PD1-1		1	1		REG FILE 02	1	1	
	RES/DSIR/EIB		1	1		RGN3 FILE 01	1	1	
EXTERNAL:	NRC PDR		1	1		NSIC	1	1	

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 12 ENCL 12-0



AEP:NRC:1056F

Donald C. Cook Nuclear Plant Unit 1
Docket No. 50-315
License No. DPR-58
NRC BULLETIN NO. 88-02, "RAPIDLY PROPAGATING
FATIGUE CRACKS IN STEAM GENERATOR TUBES"

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Attn: W. T. Russell

June 28, 1994


Dear Mr. Russell:

Reference: Letter, J. B. Hickman (NRC) to E. E. Fitzpatrick
(I&M), April 15, 1994.

The referenced letter transmitted NRC acceptance of our responses to NRC Bulletin 88-02, entitled "Rapidly Propagating Fatigue Cracks in Steam Generator Tubes". The letter requested that we 1) inform the NRC when we have removed steam generator tube R8C35 from service, and 2) establish administrative controls to ensure that updated stress ratio and fatigue usage calculations are performed in the event of any significant changes to the steam generator operating parameters, or inform the NRC if administrative controls will not be established.

Steam generator tube R8C35 was removed from service during the Unit 1 Cycle 13-14 refueling outage. Also, administrative controls have been established as requested.

Sincerely,

for 
E. E. Fitzpatrick
Vice President

ajf i:\nsl\letter\1056f.msa

9407060158 940628
PDR ADOCK 05000315
PDR

IEI/B
1/0

Mr. W. T. Russell

2

AEP:NRC:1056F

cc: A. A. Blind
G. Charnoff
J. B. Martin - Region III
NFEM Section Chief
NRC Resident Inspector - Bridgman
J. R. Padgett