

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9103040344 DOC.DATE: 91/02/26 NOTARIZED: NO DOCKET #
 FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316
 AUTH.NAME AUTHOR AFFILIATION
 BAKER,D.L. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele
 RECIP.NAME RECIPIENT AFFILIATION
 MORLEY,F. Michigan, State of

SUBJECT: NPDES noncompliance notification: on 910220 & 21, unmonitored
 discharges occurred from turbine room sump. Caused by
 inoperable pH meter. Turbine sump room isolated & job order
 written to repair meter.

DISTRIBUTION CODE: IE23D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: Environmental Event Report (per Tech Specs)

NOTES:

	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTTR	ENCL		LTTR	ENCL
	PD3-1 LA	3	3	PD3-1 PD	1	1
	COLBURN, T.	1	1			
INTERNAL:	AEOD/DSP/TPAB	1	1	AEOD/PTB	1	1
	NRR/DREP/PEPB9D	1	1	NRR/PMAS/ILRB12	1	1
	OGC/HDS2	1	1	REG FILE 01	1	1
	RGN3	1	1	RGN2/DRSS/EPRPB	1	1
EXTERNAL:	NRC PDR	1	1	NSIC	1	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 15 ENCL 15 0

Indiana Michigan
Power Company
One Summit Square
P.O. Box 60
Fort Wayne, IN 46801
219 425 2111



February 26, 1991

Fred Morley, District Supervisor
Surface Water Quality Division
Michigan Department of Natural Resources
621 North 10th Street
P.O. Box 355
Plainwell, MI 49080

Dear Mr. Morley:

RE: NPDES Permit No. MI 0005827
Cook Nuclear Plant
Bridgman, Michigan

Between the hours of 0745 - 1324 and 1651 - 1955 on February 20, 1991, and 0022 and 0750 on February 21, 1991, unmonitored discharges occurred from the Turbine Room Sump (TRS). These resulted from an inoperable pH meter, which was discovered during the daily calibration check on February 21. The Turbine Room Sump was isolated immediately upon discovery and a job order was written to repair the pH meter. In the interim, discharges from the Sump are being manually sampled for pH. An estimated 700,000 gallons of water were released prior to the sump isolation.

We have no reason to believe that any effluent limitations were exceeded during this period.

Very truly yours,

A handwritten signature in cursive script that reads 'Donald L. Baker'.

Donald L. Baker
Environmental Affairs Director

DLB/cyj

c: A. B. Davis - NRC Region III
J. A. Isom - NRC Resident Inspector
Dr. T. E. Murley -- NRR
NRC Document Control

9103040344 910226
PDR -ADOCK 05000315
S PDR

IF 2/23
1/0

