

REGULATORY INFORMATION DISTRIBUTION SYSTEM

DOCKET NBR: 50251 TURKEY PT#4
RECIPIENT: OREILLY, J.P.
ORIGINATOR: SCHMIDT, A.D.
COMPANY NAME: FL PWR & LIGHT
SUBJECT:

DOC DATE: 781011
ACCESSION NBR: 7810200093
COPIES RECEIVED:
LTR 1 ENCL 1
SIZE: 1+1

LER#78-010/031-0 on 780911: Leakage of radioactively contaminated water to paved area outside of pump room for 30 minutes, caused by spent fuel pit cooling pump mech seal failure.

DISTRIBUTION CODE: A002
DISTRIBUTION TITLE:
INCIDENT REPORTS

NOTARIZED

NAME	ENCL?
BR CHIEF	W/4 ENCL
REG FILE	W/ENCL
NRC PDR	W/ENCL
I & E	W/2 ENCL
MIPC	W/3 ENCL
I & C SYSTEMS BR	W/ENCL
EMERGENCY PLAN BR	W/ENCL
NOYAK/CHECK	W/ENCL
EEB	W/ENCL
AD FOR ENG	W/ENCL
PLANT SYSTEMS BR	W/ENCL
HANAUER	W/ENCL
AD FOR PLANT SYSTEMS	W/ENCL
AD FOR SYS & PROJ	W/ENCL
REACTOR SAFETY BR	W/ENCL
ENGINEERING BR	W/ENCL
VOLLMER/BUNCH	W/ENCL
KREGER/J. COLLINS	W/ENCL
POWER SYS BR	W/ENCL
K SEYFRIT/IE	W/ENCL
LPDR	W/ENCL
NSIC	W/ENCL
ACRS	W/16 ENCL

FOR ACTION

ORB#1 BC

TOTAL NUMBER OF COPIES REQUIRED:

LTR 44
ENCL 44

OCT 23 1978

NOTES:



October 11, 1978

PRN-LI-78-294

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 251-78-10
TURKEY POINT UNIT 4
DATE OF OCCURRENCE: SEPTEMBER 11, 1978

SPENT FUEL PIT COOLING PUMP
MECHANICAL SEAL FAILURE

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9.2 to provide 30 day notification of the subject occurrence..

Very truly yours,

E. D. Schmidt
E. D. Schmidt
Vice President
Power Resources

REGULATORY DOCKET FILE COPY

WAK/mld

Attachment

cc: Robert Lowenstein, Esquire
Director, Office of Inspection and Enforcement (30)
✓ Director, Office of Management Information and
Program Control (3)

REGULATORY DOCKET FILE COPY

7810200093

A002
5/11

