

# REGULATOR INFORMATION DISTRIBUTION ITEM (RIDS)

ACCESSION NBR: 7906140384 DOC. DATE: 79/05/21 NOTARIZED: NO DOCKET #  
 FACIL: 50-251 Turkey Point Plant, Unit 4, Florida Power and Light Co 05000251  
 AUTH. NAME: YAEGER, M.K. AUTHOR AFFILIATION: Florida Power & Light Co.  
 RECIP. NAME: O'REILLY, J.P. RECIPIENT AFFILIATION: Region 2, Atlanta, Office of the Director


SUBJECT: RO 251-79-07 on 790519: pipe support in charging pump room inoperable. Full rept & corrective action to be submitted in response to IE Bulletin 79-02.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 7 ENCL 0 SIZE: 11  
 TITLE: INCIDENT REPORTS

NOTES: -----

ACTION:	RECIPIENT		COPIES		RECIPIENT	COPIES	
	ID CODE/NAME		LTTR	ENCL	ID CODE/NAME	LTTR	ENCL
ACTION:	05 BC ORB #1		4	4			
INTERNAL:	01 REG. FILE		1	1	02 NRC PDR	1	1
	09 I&E		2	2	11 MPA	3	3
	14 TA/EDO		1	1	15 NOVAK/KNIEL	1	1
	16 EEB		1	1	17 AD FOR ENGR	1	1
	18 PLANT SYS BR		1	1	19 I&C SYS BR	1	1
	20 AD PLANT SYS		1	1	21 AD SYS/PROJ	1	1
	22 REAC SAFT BR		1	1	23 ENGR BR	1	1
	24 KREGER		1	1	25 PWR SYS BR	1	1
	26 AD/SITE ANAL		1	1	27 OPERA LIC BR	1	1
	28 ACIDENT ANALYS		1	1	29 AUX SYS BR	1	1
	E JORDAN/IE		1	1	HANAUER, S.	1	1
	TMI DOC CENTER		1	1			
EXTERNAL:	03 LPDR		1	1	04 NSIC	1	1
	29 ACRS		16	16			


JUN 15 1979  
 a04  
 CCP



1EHQS

USNRC REGION  
ATLANTA, GEORGIA

P.O. BOX 2100 MIAMI, FLORIDA 33



WTP-QC-79-24  
Turkey Point Plant  
May 21, 1979

19 MAY 21 P 3:57

TO: Mr. J. P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Atlanta, Georgia 30303

FROM: Mr. E. E. Yeager, Plant Manager  
Turkey Point Plant - DEX 31441  
Florida Power & Light Company  
Miami, Florida

SUBJECT: MEMO FOR FACSIMILE TRANSMISSION TO CONFIRM  
REPORTABLE OCCURRENCE 79-02

This memo confirms our telephone notification of the subject prompt notification reportable occurrence made Saturday May 19, 1979 to Mr. E. E. Wordery of your office as follows:

OCCURRENCE - On Saturday May 19, 1979, the first inoperable pipe support was reported by the team conducting the inspection/evaluation in accordance with our procedure developed to comply with I & E Bulletin 79-02. The specific inoperable support is designated A-PC2-105 and is associated with the 3 inch charging line in the Unit 4 charging pump room. On this support, a two bolt plate attachment to a concrete wall is displaced about 1/8 inch from the wall with one bolt missing and the other bolt loose.

CORRECTIVE ACTION - This pipe support as well as any others found to be defective will be restored in accordance with approved repair or modification procedures. It is presently planned to complete this work prior to the end of the current Unit 4 refueling outage before power operation is resumed. A full accounting of inspection results and repairs will be made in the response to I & E Bulletin 79-02.

*[Signature]*  
E. E. Yeager  
Plant Manager

MEY:JEN:ar

REGULATORY LOG COPY

- A. P. O'REILLY
- ~~W. B. KENNA~~
- G. M. UPRIGHT
- P. D. CHENDENI
- W. B. KENNA
- F. J. LONG
- E. MURPHY
- T. SUTHERLAND
- K. M. CLARK
- Lewis*
- Subson*

4002  
5/10

7906140384



Sum

