



2 PSC 26 AD: 25

December 21, 1979
L-79-361

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:


Re: RII:JPO
50-250, 50-251
IE Bulletin 79-14

For your information, we are reporting the status of our work on the subject Bulletin.

Accessible piping outside of containment has been inspected and evaluated for both Turkey Point Units 3 and 4. Final Unit 3 inspections are being conducted during the current refueling outage. Final Unit 4 inspections are planned for a future outage of sufficient duration, which is expected to be the next steam generator inspection outage. The evaluations for the inspections will be performed by our Architect/Engineer, and each Unit's evaluation should be completed about 30 days after the completion of the respective inspection.

Please call if you have further questions on this subject.

Very truly yours,



Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/MAS/ms

cc: Harold Reis, Esquire

8001180 208
Q790884 ADZ
OFFICIAL COPY

PEOPLE...SERVING PEOPLE KB

