

CONTROL BLOCK: | | | | | | | ① (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[illegible]

8004240 317.



REPORTABLE OCCURRENCE 250-80-06  
LICENSEE EVENT REPORT  
PAGE TWO

Additional Cause Description and Corrective Actions:

The failure to fully perform the surveillance resulted from a misunderstanding of the surveillance division of responsibility following a restructuring of the onsite organization. The 4 PIVs involved are in the alternate flow path surrounding fossil Unit Nos. 1 & 2. The personnel responsible for this surveillance have been instructed to surveil those TS items associated with the fossil units.

