

USNRC REGION I
ATLANTA, GEORGIA



30 MAR 24 AIO: 41

March 21, 1980
L-80-99

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:SAE
50-250/80-3
50-251/80-3

Florida Power & Light Company has reviewed the subject inspection report and a response is attached.

There is no proprietary information in the report.

Very truly yours,

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/GDW/ah

Attachment

cc: Harold F. Reis, Esquire

8004240378

OFFICIAL COPY

ATTACHMENT

Re: RII:SAE
50-250/80-3
50-251/80-3

Finding

Based on the results of the NRC inspection conducted on January 7-11, 1980, certain of your activities appear to deviate from your commitments to the Commission

NRC letter of February 5, 1978, "Fire Protection Guidelines," Attachment 6; Florida Power & Light Company's (FP&L) response letter L-78-197, "Fire Protection Guidelines," Enclosure 1, section labeled "attachment 6"; and NRC confirming letter of June 30, 1978, "Fire Protection Guidelines" comprise a commitment made and accepted that FP&L establish a Fire Protection Quality Assurance (FPQA) Program based on draft Regulatory Guide 1.120, June 1976 with a "levels of quality" approach.

Contrary to the above, during the week of January 7-11, 1980, the licensee could furnish no evidence of completed FPQA Program development and implementation.

Response

As corrective action, a Fire Protection Quality Assurance Program will be developed and implemented at Turkey Point by July 31, 1980.

A recently implemented system for tracking commitments to the NRC should prevent future deviations of this type.

Compliance will be achieved by July 31, 1980.

