

8005050 220 Q

P.O. BOX 529100, MIAMI, FL 33152

USNRC REGION II  
ATLANTA, GEORGIA



80 MAR 5 AIO: 52

March 3, 1980  
L-80-69

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

RE: RII: RVL  
50-250/79-41  
50-251/79-41

Florida Power & Light Company has reviewed the subject inspection report and a response is attached.

There is no proprietary information in the report.

Very truly yours,

Robert E. Uhrig  
Vice President  
Advanced Systems & Technology

REU/MAS/pa.

Attachment

cc: Harold Reis, Esquire

OFFICIAL COPY.

PEOPLE...SERVING PEOPLE



ATTACHMENT

RE: RII:RVL  
50-250/79-41  
50-251/79-41

Finding:

As required by Technical Specification 6.8.1, written procedures and administrative policies shall be implemented. Paragraph 8.4.6.1.1 of Administrative Procedure 0103.2 requires that all recorder charts be stamped with the date and identification.

Contrary to the above, recorder charts 454, 455, 456 associated with the steam generator parameters gathered during and subsequent to the 1:37 a.m. Unit 4 reactor trip on December 19, 1979, were neither stamped or labeled with any identification or dates.

Response:

As corrective action, the charts listed in the finding have been stamped and labeled as required by Administrative Procedure 0103.2.

In order to prevent recurrence, discussions were held with the appropriate Nuclear Watch Engineer and Nuclear Supervisor on the importance of full compliance with Administrative Procedure 0103.2.

Compliance was achieved on February 19, 1980.

