


USNRC REGION II
ATLANTA, GEORGIA

30 SEP 8 A10:12



September 2, 1980
L-80-286

Central File

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:JBO
50-250, 50-251
IE Bulletin 80-19, Rev. 1

Florida Power & Light Company has reviewed the Turkey Point facility as requested by the subject Bulletin and has determined that no C. P. Clare Model HG2X-1011 mercury-wetted relays are used in the logic matrix of the RPS. Four manhours were expended in preparing this response.

Very truly yours,

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/PLP/cph

cc: Harold Reis, Esquire

OFFICIAL COPY

PEOPLE...SERVING PEOPLE

8:009120671

