

GENRO REG  
ATLANTA, GEORGIA

0 OCT 6 AM: 03



FLORIDA POWER & LIGHT COMPANY

September 23, 1980

L-80-315

*Central File*

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly

Re: RII:OPD  
50-250, 50-251  
IE Bulletin 80-18

Florida Power & Light has reviewed the subject Bulletin and has determined that it is not applicable to the Turkey Point units. The units do not have centrifugal charging pumps, and the recirculation lines on the safety injection pumps are not isolated on receipt of the Safety Injection Actuation Signal. Five man-hours were expended preparing this report.

Very truly yours,

*J. A. De Mastey*  
*on.*

Robert E. Uhrig  
Vice President  
Advanced Systems & Technology

REU/PLP/ras

cc: Director, NRC Office of Inspection and Enforcement  
Division of Reactor Operations Inspection  
Harold Reis, Esquire

*D*

OFFICIAL COPY

8010240648

*Q*

PEOPLE...SERVING PEOPLE