

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 FLTPS 3 2000-000000-000341111145
7 3 9 14 15 25 25 30 37 CAT 38

CON'T
01 REPORT SOURCE L 805000250711018031128809
7 3 60 61 63 63 65 65 67 67 69 69

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
02 During performance of OP 14004.5, Seismograph -Periodic Test, to implement
03 TS 4.1 (Table 4.1-1, Item 26), the seismograph was found to be inoperable
04 following an initial successful calibration check. The batteries in the
05 unit were found to be discharged. Alternate means of recording seismic
06 events are available at the site. Public health safety were not effected.
07
08
09
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
09 XX 11 E 12 A 13 INSTRU 14 X 15 Z 16

17 LEAD REPORT NUMBER 80
21 22
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS (22) ATTACHMENT SUBMITTED NRC-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
10 Z 19 1/2 20 Z 21 00000 N 23 N 24 A 25 K1300

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10 The cause of the discharged batteries was found to be an electrical
11 problem in the seismograph. The assembly has been returned to the
12 manufacturer for expedited repair.
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47

FACILITY STATUS 15 G 28 0000 29 NA OTHER STATUS 30 NA METHOD OF DISCOVERY 31 B 32 Surveillance test
7 3 9 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

ACTIVITY CONTENT 15 Z 33 Z 34 NA AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36 NA
7 3 1 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

PERSONNEL INVOLVED 17 0100 38 12 39 NA
7 3 1 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

PERSONNEL INVOLVED 17 010 40 NA
7 3 1 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

DAMAGE TO FACILITY 17 01 42 NA
7 3 1 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

DESCRIPTION 17 01 45 NA
7 3 1 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

NRC USE ONLY
20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

NAME OF PREPAPER P.L. Pace PHONE: (305) 552-3801

8101050342

