



PRP-QC-81-003  
Turkey Point Plant  
January 6, 1981

Mr. J. P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Atlanta, Georgia 30303

Mr. J. K. Hays, Plant Manager - Nuclear  
Turkey Point Plant - DPA 31 and 41  
Florida Power and Light Company  
Miami, Florida

Director  
Deputy Director  
Ass't to Director  
Admin. Officer  
RONS Chief  
RCES Chief  
FFMS Chief  
Sfgds Chief  
P A Officer

11 JAN 7 1981  
P 3:21

USNRC REGION II  
ATLANTA, GEORGIA

SUBJECT: MEMO FOR FACSIMILE TRANSMISSION TO CONFIRM  
REPORTABLE OCCURRENCE 250-81-3

MEMO confirms our notification of the subject prompt notification reportable  
occurrence made yesterday to Mr. C. Julian of your office as follows:

REFERENCE

Monday, January 5, 1981, in the course of investigating potential cracks observed in  
Lexan coil spools of General Electric Company type HFA relays, a new coil assembly in  
the parts storage was confirmed to have a crack in the spool end plate.

EFFECTIVE ACTION

operational failures of this type relay due to coil spool cracks have been  
experienced. An inspection program for all relays of this type is being developed and  
initiated.

  
J. K. Hays  
Plant Manager - Nuclear

Code

8103060325

