


USNRC REGION II  
ATLANTA, GEORGIA



81 AUG 4 A 9:10

July 28, 1981  
L-81-324

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: Turkey Point Units 3 & 4  
Docket Nos. 50-250, 50-251  
IE Inspection Report 81-11

This letter supplements our June 30, 1981 response to Inspection Report 50-250/81-11 and 50-251/81-11 as discussed in our July 15, 1981 telephone call with your Mr. W. H. Miller and Mr. Hugh Dance. With respect to the last finding, we will implement the requirements of Technical Specification 4.15.1.a proposed in our March 10, 1981 Letter (L-81-111) to Mr. Darrell G. Eisenhut. Our current plans are to implement the new requirement within sixty days and to complete the next semiannual test of fire detectors during the next refueling outage on Unit 4 and during the current outage on Unit 3.

Very truly yours,

Robert E. Uhrig  
Vice President  
Advanced Systems & Technology

REU/PLP/ah

cc: Harold F. Reis, Esquire

8109010345 810814  
PDR ADDCK 05000250  
Q PDR

