

# REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8109280234 DOC. DATE: 81/09/21. NOTARIZED: NO DOCKET #  
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light Co. 05000250  
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light Co. 05000251  
 AUTH. NAME: UHRIG, R. E. AUTHOR AFFILIATION: Florida Power & Light Co.  
 RECIP. NAME: EISENHUT, D. G. RECIPIENT AFFILIATION: Division of Licensing

SUBJECT: Discusses actions taken while work continues w/Westinghouse owners group; re emergency procedures & training for station blackout events, per NRC 810826 ltr. Training rept issued to licensed operators describing alternative ac power sources.

DISTRIBUTION CODE: A0016 COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2  
 TITLE: General Distribution for after Issuance of Operating License

## NOTES:

ACTION:	RECIPIENT ID CODE/NAME		COPIES		RECIPIENT ID CODE/NAME	COPIES	
			LTR	ENCL		LTR	ENCL
ACTION:	ORBI #1 BCI	04	13	13			
INTERNAL:	D/DIR, HUM FACD8		1	1	DIR, DIV OF LIC	1	1
	I&EI	06	2	2	OELD	1	1
	OR ASSESS BR		1	1	RAD ASMT BR	1	1
	REF. FILE	01	1	1			
EXTERNAL:	ACRS	09	16	16	LPDR	03	1
	NRC PDRI	02	1	1	NSIC	05	1
	NTIS		1	1			

SEP 30 1981

TOTAL NUMBER OF COPIES REQUIRED: LTR 41 ENCL 3


1. The first part of the report is a summary of the work done during the year. It is a brief statement of the facts and figures, and is intended to give a general impression of the work done. It is not a detailed account of the work, but a summary of the main results.

2. The second part of the report is a detailed account of the work done during the year. It is a full and complete statement of the facts and figures, and is intended to give a detailed account of the work done. It is not a summary of the work, but a full and complete statement of the facts and figures.

3. The third part of the report is a statement of the conclusions reached during the year. It is a brief statement of the main results, and is intended to give a general impression of the work done. It is not a detailed account of the work, but a summary of the main results.

4. The fourth part of the report is a statement of the recommendations made during the year. It is a brief statement of the main results, and is intended to give a general impression of the work done. It is not a detailed account of the work, but a summary of the main results.

GENERAL INFORMATION		DETAILS OF WORK		RESULTS	
DATE	DESCRIPTION	DATE	DESCRIPTION	DATE	DESCRIPTION
1	1	1	1	1	1
2	2	2	2	2	2
3	3	3	3	3	3
4	4	4	4	4	4
5	5	5	5	5	5
6	6	6	6	6	6
7	7	7	7	7	7
8	8	8	8	8	8
9	9	9	9	9	9
10	10	10	10	10	10




September 21, 1981  
L-81-412

Office of Nuclear Reactor Regulation  
Attention: Mr. Darrell G. Eisenhut, Director  
Division of Licensing  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Dear Mr. Eisenhut:

Re: Turkey Point Units 3 & 4  
Docket Nos. 50-250 & 50-251  
Emergency Procedures and Training  
For Station Blackout Events



Florida Power & Light has reviewed the NRC letter dated August 26, 1981 concerning Station Blackout. We are continuing to work with the Westinghouse Owner's Group regarding preparation of emergency procedures and training for station blackout events.


While this work is underway, however, we will take additional actions at Turkey Point to address this issue. We have issued a training report to all licensed operators which describes the availability of alternative AC power sources on the site. These sources can be used to supply vital loads in the event of the loss of all normal AC power sources. The training report covers the following items:

1. systems which are lost due to station blackout,
2. prompt operator actions which are required,
3. availability and capacity of alternative power sources,
4. general method for connecting alternative power supplies.

In addition to the issuance of the training report, a lecture segment on Plant Blackout will be presented to each operating shift during the six week requalification cycle which is scheduled to begin September 28, 1981. This lecture segment will familiarize the operator with the actions required in the event of a station blackout including necessary breaker lineups.

A001  
s  
1/0

8109280234 810921  
PDR ADOCK 05000250  
F PDR



THE  
FEDERAL

Mr. Darrell G. Eisen, Director  
Page 2

It is our opinion that because of the availability of these alternative power sources at Turkey Point, the above actions are sufficient until our actions in conjunction with the Westinghouse Owner's Group are completed in January 1982. By refraining from making actual procedure changes for the short period until the Owners' Group work is done, we will also minimize the chance for operator confusion which could result from consecutive procedure changes.

Very truly yours,

*J. A. De Monty*  
*or*

Robert E. Uhrig  
Vice President  
Advanced Systems & Technology

REU/PLP/ras

cc: Mr. J. P. O'Reilly, Region II  
Harold F. Reis, Esquire

