

# REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8208160296 DOC.DATE: 82/08/09 NOTARIZED: NO DOCKET #  
 FACIL:50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251  
 AUTH.NAME AUTHOR AFFILIATION  
 UHRIG,R.E. Florida Power & Light Co.  
 RECIP.NAME RECIPIENT AFFILIATION  
 EISENHUT,D.G. Division of Licensing

SUBJECT: Forwards "Repts of Steam Generator Insp & Tube Repair - Jul 1982 Outage."

DISTRIBUTION CODE: A001S COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1+40  
 TITLE: General Distribution for after Issuance of Operating License

## NOTES:

	RECIPIENT ID CODE/NAME		COPIES LTTR ENCL		RECIPIENT ID CODE/NAME		COPIES LTTR ENCL
	ORB #1 BC	01	7	7			
INTERNAL:	ELD/HDS4		1	0	NRR/DHFS DEPY08		1 1
	NRR/DL DIR		1	1	<del>NRR/DL ORAB</del>		1 0
	NRR/DSI/RAB		1	1	<u>REG FILE</u>	04	1 1
	RGN2		1	1			
EXTERNAL:	ACRS	09	10	10	LPDR	03	1 1
	NRC PDR	02	1	1	NSIC	05	1 1
	NTIS		1	1			

THE  
UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
WASHINGTON, D. C. 20240

TO: [illegible]  
FROM: [illegible]  
SUBJECT: [illegible]


[illegible text]

[illegible text]

[illegible text]

[illegible text]

[illegible text]



August 9, 1982  
L-82-336

Office of Nuclear Reactor Regulation  
Attention: Mr. Darrell G. Eisenhower, Director  
Division of Licensing  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Dear Mr. Eisenhower:

Re: Turkey Point Unit 4  
Docket No. 50-251  
Report of Steam Generator Inspection and Tube Repair

Please find attached the subject report pursuant to Section 3.D.5 of DPR-41. The Report describes our program of: (1) visual inspection of the secondary side of the three steam generators using fiber optics; (2) locating and removing all significant foreign material; (3) eddy current inspections in all three steam generators of peripheral tubes and wedge areas and areas to bound debris location; (4) conservative plugging; (5) installation of a metal impact monitoring system on all three steam generators.

The described program and the results of all inspections performed support continued full power operation of Turkey Point Unit 4 well beyond the planned operating interval (through approximately mid-October, 1982) without undue risk to the health and safety of the public. This determination has been concurred with by our NSSS vendor, and has been reviewed and approved by the Plant Nuclear Safety Committee and Company Nuclear Review Board.

Very truly yours,

Robert E. Uhrig  
Vice President  
Advanced Systems and Technology

*Aool*

REU/JEM/mbd

Attachment

cc: Mr. James P. O'Reilly, Region II  
Mr. Harold F. Reis, Esquire

8208160296 820809  
PDR ADOCK 05000251  
Q PDR



