



MAY 15 1986  
L-86-203

PDR

Dr. J. Nelson Grace  
Regional Administrator, Region II  
U. S. Nuclear Regulatory Commission  
101 Marietta Street N.W., Suite 2900  
Atlanta, Georgia 30323

Re: Turkey Point Units 3 and 4  
Docket Nos. 50-250 and 50-251  
IE Bulletin 85-03

Dear Dr. Grace:

We are currently reviewing IE Bulletin 85-03 (Motor-Operated Valve Common Mode Failures During Plant Transients Due to Improper Switch Settings) as it applies to Turkey Point Units 3 and 4. As discussed with your staff, to allow for thorough FPL review of the response requested by the bulletin we are planning to submit it by May 25, 1986.

Should you or your staff have any questions on this information, please contact us.

Very truly yours,

C. O. Woody  
Group Vice President  
Nuclear Energy

COW/SAV:de

Attachment

cc: Harold F. Reis, Esquire  
USNRC Document Control Desk  
PNS-LI-86-157

8607230393 860515  
PDR ADDCK 05000250  
Q PDR



