

# UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50-250

UNIT NAME Turkey Point Unit #3

DATE November 15, 1988

COMPLETED BY D. M. Bonett

TELEPHONE (407) 694-4432

**\*\*CORRECTED COPY\*\***

REPORT MONTH October, 1988

No.	Date	Type <sup>1</sup>	Duration (Hours)	Reason <sup>2</sup>	Method of Shutting Down Reactor <sup>3</sup>	Licensee Event Report #	System Code <sup>4</sup>	Component Code <sup>5</sup>	Cause & Corrective Action to Prevent Recurrence
10	881001	F	723.6	A	1	250-88-024	CF	PUMPXX	<p>During the monthly Residual Heat Removal Pump (RHR) inservice test, seal leakage in the 3A RHR pump resulted in the pump being declared out of service. The unit was shut down and the 3A RHR pump leaking seal was replaced with a spare shaft seal.</p> <p>The outage was further extended to repair the pressurizer heaters and replace electrical generator rotor.</p>

1

F Forced  
S Scheduled

2

Reason  
A - Equipment Failure (Explain)  
B - Maintenance or Test  
C - Refueling  
D - Regulatory Restriction  
E - Operator Training & License Examination  
F - Administrative  
G - Operational Error (Explain)  
H - Other (Explain)

3

Method  
1 - Manual  
2 - Manual Scram  
3 - Automatic Scram  
4 - Continued  
5 - Load Reduction  
9 - Other (Explain)

4

Exhibit G - Instructions  
for Preparation of Data  
Entry Sheets Licensee  
Event Report (LER) File  
(NUREG-0161)

5

Exhibit 1 - Same Source

8812200015 881213  
PDR ADDCK 05000250  
PDC

