

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8305100001 DOC.DATE: 83/05/06 NOTARIZED: NO DOCKET #
 FACIL:50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH.NAME AUTHOR AFFILIATION
 UHRIG,R.E. Florida Power & Light Co.
 RECIP.NAME RECIPIENT AFFILIATION
 EISENHUT,D.G. Division of Licensing

SUBJECT: Submits steam generator repair program cleanliness rept.
 Post-contamination & final loop insps & steam generator
 search & retrieval accomplished to meet primary & secondary
 side cleanliness commitments.

DISTRIBUTION CODE: A001S COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1
 TITLE: OR Submittal: General Distribution

NOTES:

	RECIPIENT ID CODE/NAME		COPIES LTTR ENCL		RECIPIENT ID CODE/NAME		COPIES LTTR ENCL
	NRR ORB1 BC 01		7 7				
INTERNAL:	ELD/HDS4		1 0		NRR/DE/MTEB		1 1
	NRR/DL DIR		1 1		NRR/DL/ORAB		1 0
	NRR/DSI/METB		1 1		NRR/DSI/RAB		1 1
	<u>REG FILE</u> 04		1 1		RGN2		1 1
EXTERNAL:	ACRS 09	6 6		LPDR 03		1 1	
	NRC PDR 02	1 1		NSIC 05		1 1	
	NTIS	1 1					

THE
UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
WASHINGTON, D. C. 20240

TO: DIRECTOR, BUREAU OF LAND MANAGEMENT
FROM: SAC, [illegible]
SUBJECT: [illegible]

RE: [illegible]

2011

DATE	INITIALS	REMARKS
10/10/11	[illegible]	[illegible]
10/11/11	[illegible]	[illegible]
10/12/11	[illegible]	[illegible]
10/13/11	[illegible]	[illegible]
10/14/11	[illegible]	[illegible]
10/15/11	[illegible]	[illegible]
10/16/11	[illegible]	[illegible]
10/17/11	[illegible]	[illegible]
10/18/11	[illegible]	[illegible]
10/19/11	[illegible]	[illegible]
10/20/11	[illegible]	[illegible]
10/21/11	[illegible]	[illegible]
10/22/11	[illegible]	[illegible]
10/23/11	[illegible]	[illegible]
10/24/11	[illegible]	[illegible]
10/25/11	[illegible]	[illegible]
10/26/11	[illegible]	[illegible]
10/27/11	[illegible]	[illegible]
10/28/11	[illegible]	[illegible]
10/29/11	[illegible]	[illegible]
10/30/11	[illegible]	[illegible]
10/31/11	[illegible]	[illegible]



FLORIDA POWER & LIGHT COMPANY

May 6, 1983
L-83-289

Office of Nuclear Reactor Regulation
Attention: Mr. Darrell G. Eisenhut, Director
Division of Licensing
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Mr. Eisenhut:

Re: Turkey Point Units 3 & 4
Docket Nos. 50-250 & 50-251
Steam Generator Repair
Program Cleanliness Report

Our letter L-83-72, dated February 11, 1983, transmitted the bulk of the information required in Section 3.H.2.h.vi of DPR-41 regarding cleanliness of the steam generators following the repair. The final loop inspections designed to indicate that commitments to primary and secondary side cleanliness have been met are:

- 1) Post-decontamination and final loop inspections have been accomplished in accordance with Westinghouse procedure MRS 2.2.2 FLA-1.
- 2) Steam Generator search and retrieval has been accomplished in accordance with Westinghouse Procedure SP 2.4.2 GEN-4.

All documentation is available on site for your inspection.

Very truly yours,

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/JEM/cab

cc: Mr. James P. O'Reilly, Region II
Mr. Harold F. Reis, Esquire

Pool

8305100001 830506
PDR ADOCK 05000250
Q PDR



