

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8306210071 DOC. DATE: 83/06/16 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH. NAME AUTHOR AFFILIATION
 UHRIG, R.E. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 DENTON, H.R. Office of Nuclear Reactor Regulation, Director


SUBJECT: RO: on 830516, several fire barrier penetrations breached for longer than 7 days. Caused by implementation of design changer, including new computer room & auxiliary power upgrade. Hourly fire watch established.

DISTRIBUTION CODE: A006S COPIES RECEIVED: LTTR 1 ENCL 0 SIZE: 1/1
 TITLE: OR Submittal: Fire Protection

NOTES:

	RECIPIENT ID CODE/NAME		COPIES			RECIPIENT ID CODE/NAME		COPIES	
			LTTR	ENCL				LTTR	ENCL
	NRR ORB1 BC 01		3	3					
INTERNAL:	ELD/HDS4		1	0		IE FILE 06		1	1
	IE/WHITNEY, L		1	1		NRR FIORAVANT07		2	2
	NRR WAMBACH		1	0		NRR/DE/CEB 09		2	2
	NRR/DL DIR		1	1		REG FILE 04		1	1
	RGN2		1	1					
EXTERNAL:	ACRS 11		3	3		LPDR 03		1	1
	NRC PDR 02		1	1		NSIC 05		1	1
	NTIS		1	1					

TOTAL NUMBER OF COPIES REQUIRED: LTTR 21 ENCL 0





June 16, 1983
L-83-364

58-250
58-251

Dr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dear Dr. Denton:

SPECIAL REPORT

Turkey Point Units 3 & 4

Date of Occurrence: May 16, 1983

Technical Specification 3.14.5.b

FIRE BARRIER PENETRATIONS

This special report is being submitted in accordance with Technical Specification 6.9.3 to provide 30 days notification on the subject occurrence.

Due to the implementation of approved design changes which included the new computer room and auxiliary power upgrade, several fire barrier penetrations were breached for longer than seven days. The penetrations are located at the Unit 3 and Unit 4 B-MCC rooms, Unit 4 4160 V switchgear rooms, Unit 4 electrical penetration rooms (4N) and (4W) and Auxiliary Building east and west hallway walls above the double doors.

Our ability to return the breached penetrations to functional status depends on the time frame required to complete the implementation of the design changes. The projected duration is three months from the date of this report. In compliance with Technical Specifications, an hourly fire watch has been established.

Very truly yours,

J. a. de Mastry
on

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/SAV/cab

cc: J. P. O'Reilly, Region II
Harold F. Reis, Esquire

A006
1/0

8306210071 830616
PDR ADDCK 05000250
S PDR

