

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8902150008 DOC. DATE: 89/02/07 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH. NAME: CONWAY, W.F. AUTHOR AFFILIATION: Florida Power & Light Co.
 RECIP. NAME: RECIP. AFFILIATION: Document Control Branch (Document Control Desk)

SUBJECT: Special rept: on 890131, fire protection sys impairments occurred.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
 TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES		
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME		LTTR	ENCL	
	PD2-2 LA		1	1		PD2-2 PD		1	1	
	EDISON, G		1	1						
INTERNAL:	ACRS MICHELSON		1	1		ACRS MOELLER		2	2	
	ACRS WYLIE		1	1		AEOD/DOA		1	1	
	AEOD/DSP/TPAB		1	1		AEOD/ROAB/DSP		2	2	
	ARM/DCTS/DAB		1	1		DEDRO		1	1	
	NRR/DEST/ADE 8H		1	1		NRR/DEST/ADS 7E		1	0	
	NRR/DEST/CEB 8H		1	1		NRR/DEST/ESB 8D		1	1	
	NRR/DEST/ICSB 7		1	1		NRR/DEST/MEB 9H		1	1	
	NRR/DEST/MTB 9H		1	1		NRR/DEST/PSB 8D		1	1	
	NRR/DEST/RSB 8E		1	1		NRR/DEST/SGB 8D		1	1	
	NRR/DLPQ/HFB 10		1	1		NRR/DLPQ/QAB 10		1	1	
	NRR/DOEA/EAB 11		1	1		NRR/DREP/RAB 10		1	1	
	NRR/DREP/RPB 10		2	2		NRR/DRIS/SIB 9A		1	1	
	NUDOCS-ABSTRACT		1	1		REG FILE 02		1	1	
	RES/DSIR/EIB		1	1		RES/DSR/PRAB		1	1	
	RGN2 FILE 01		1	1						
EXTERNAL:	EG&G WILLIAMS, S		4	4		FORD BLDG HOY, A		1	1	
	H ST LOBBY WARD		1	1		LPDR		1	1	
	NRC PDR		1	1		NSIC HARRIS, J		1	1	
	NSIC MAYS, G		1	1						

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 45 ENCL 44

1/A-2



FPL

P.O. Box 14000, Juno Beach, FL 33408-0420

FEBRUARY 7 1989

L-89-35

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555


Gentlemen:

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Special Report - Breached Fire Barriers and
Other Fire Protection System Impairments

In accordance with Technical Specification 6.9.3.c, the attached Special Report is provided for your information.

Should there be any questions on this information, please contact us.

Very truly yours,


W. F. Conway
Senior Vice President - Nuclear

WFC/RHF/gp

Attachment

cc: Malcolm L. Ernst, Acting Regional Administrator, Region II,
USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

8902150008 890207
PDR ADOCK 05000250
S PDC

IE22
11

SPECIAL REPORT

JANUARY 31, 1989

FIRE PROTECTION SYSTEM IMPAIRMENTS REQUIRING NRC NOTIFICATION

PURPOSE:

Technical Specification (TS) 3.14.5.b requires the submission of a report to the NRC if a non-functional fire barrier penetration is not returned to functional status within 7 days. TS 3.14 also states that certain other conditions require NRC notification. In accordance with the above requirements, this special report is being generated in order to notify the NRC.

EVENT:

Fire Protection Impairment (FPI) Number 2227 was issued, on January 4, 1989, for holes through barrier 75F.

CAUSE AND CORRECTIVE ACTIONS:

The above impairment was caused by the implementation of a plant modification. Detector operability was verified and a fire patrol was established, in accordance with Technical Specifications.

STATUS UPDATE

FPI 1926, which identifies an impairment to penetration 045E-M007, was reported as open in FPL letter L-88-471. This FPI was closed on January 3, 1989.

