

UNIT SHUTDOWNS AND POWER REDUCTIONS

CORRECTED COPY

DOCKET NO. 50-250

UNIT NAME Turkey Point #3

DATE July 17, 1989

COMPLETED BY D. M. Bonett

TELEPHONE (407) 694-4432

REPORT MONTH June, 1989

No.	Date	Type ¹	Duration (Hours)	Reason ²	Method of Shutting Down Reactor ³	Licensee Event Report #	System Code ⁴	Component Code ⁵	Cause & Corrective Action to Prevent Recurrence
05	890504	S	568.8	A	4		SF	INSTRU	Unit 3 shutdown was further extended for the containment pressure switch repair, A RHR pump repair and MOV-863A repair. Full power operation delayed for 30% chemistry hold.
06	890626	F	0.0	A	5		HA	TURBIN	Full power operation was delayed for the adjustment of the governor oil system.

1

F Forced
S Scheduled

2

Reason
A - Equipment Failure (Explain)
B - Maintenance or Test
C - Refueling
D - Regulatory Restriction
E - Operator Training & License Examination
F - Administrative
G - Operational Error (Explain)
H - Other (Explain)

3

Method
1 - Manual
2 - Manual Scram
3 - Automatic Scram
4 - Continued
5 - Load Reduction
9 - Other (Explain)


4

Exhibit G- Instructions for Preparation of Data Entry Sheets Licensee Event Report (LER) File (NUREG-0161).

5

Exhibit 1 - Same Source

3908240045 390815
R PDR ADDCK 05000250
PIC



2

UNIT SHUTDOWNS AND POWER REDUCTIONS

CORRECTED COPY

DOCKET NO. 50-251

UNIT NAME Turkey Point #4

DATE July 17, 1989

COMPLETED BY D. M. Bonett

TELEPHONE (407) 694-4432

REPORT MONTH June, 1989

No.	Date	Type ¹	Duration (Hours)	Reason ²	Method of Shutting Down Reactor ³	Licensee Event Report #	System Code ⁴	Component Code ⁵	Cause & Corrective Action to Prevent Recurrence
13	880920	S	252.4	C	4		RC	FUELXX	Unit #4 remained shutdown for refueling and scheduled maintenance. While returning to power the unit was held for flux mapping.
14	890612	S	99.8	B	1		HA	TURBIN	The unit was shutdown for turbine overspeed test. The outage was extended to repair a turbine generator steam leak and RTD bypass loop valves. Full power operation was delayed for secondary chemistry and flux mapping.
* 15	890617	F	26.2	A	1		HA	GENERA	The unit was shutdown to repair an exciter leak. Full power operation was delayed for secondary chemistry, flux mapping and Nuclear Instrumentation calibration.

1
F Forced
S Scheduled

2
Reason
A - Equipment Failure (Explain)
B - Maintenance or Test
C - Refueling
D - Regulatory Restriction
E - Operator Training & License Examination
F - Administrative
G - Operational Error (Explain)
H - Other (Explain)

3
Method
1 - Manual
2 - Manual Scram
3 - Automatic Scram
4 - Continued
5 - Load Reduction
9 - Other (Explain)

4
Exhibit G- Instructions for Preparation of Data Entry Sheets Licensee Event Report (LER) File (NUREG-0161).

5
Exhibit 1 - Same Source



Handwritten marks or scribbles in the top right corner.

Handwritten text or marks in the lower center of the page.