

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9001160007 DOC. DATE: 89/12/29 NOTARIZED: NO DOCKET #
 FACIL: 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH. NAME: AUTHOR AFFILIATION:
 HARRIS, K.N. Florida Power & Light Co.
 RECIP. NAME: RECIPIENT AFFILIATION:
 Document Control Branch (Document Control Desk)

SUBJECT: Informs that required actions re NRC Bulletin 85-003 completed.

DISTRIBUTION CODE: IE11D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: Bulletin Response (50 DKT)

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 LA	1 0	PD2-2 PD	1 1
	EDISON, G	1 1		
INTERNAL:	AEOD/DOA	1 1	AEOD/DSP/TPAB	1 1
	NRR/DET/EMEB9H3	1 1	NRR/DOEA/OEAB11	1 1
	NRR/DOEA/OGCB11	1 1	NRR/DREP/PEPB9D	1 1
	NRR/DST/ 8E2	1 1	NRR/PMAS/ILRB12	1 1
	NUDOCS-ABSTRACT	1 1	<u>REG FILE</u> 02	1 1
	RES/DSIR/EIB	1 1	RGN2 FILE 01	1 1
EXTERNAL:	LPDR	1 1	NRC PDR	1 1
	NSIC	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 18 ENCL ~~17~~ 0



FPL

P.O. Box 14000, Juno Beach, FL 33408-0420

DEC 29 1989

L-89-317

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Unit 4
Docket No. 50-251
Motor-Operated Valve Common Mode
Failures During Plant Transient
Due to Improper Switch Settings
IE Bulletin 85-03

NRC IE Bulletin 85-03, "Motor-Operated Valve Common Mode Failures During Plant Transients Due to Improper Switch Settings," requested that licensees develop and implement a program to ensure that switch settings on certain safety-related motor-operated valves are selected, set and maintained correctly to accommodate the maximum differential pressures expected on these valves during both normal and abnormal events within the design basis.

This letter is to inform you that the required actions for Turkey Point Unit 4 have been completed.

Generic Letter 89-10, "Safety-Related Motor-Operated Valve Testing and Surveillance", issued June 28, 1989, supersedes the recommendations of Bulletin 85-03 and its supplement, and states that licensees need not make any further responses regarding the bulletin and its supplement. Accordingly, the summary report information required by Bulletin 85-03 will be available on site for Turkey Point Unit 4.

A summary report was submitted for Turkey Point Unit 3 on January 14, 1988 (FPL Letter No. L-88-52).

Should there be any questions, please contact us.

Very truly yours,

K. N. Harris
Vice President
Turkey Point Plant Nuclear

KNH/TCG/gp

9001160007 891229
PDR ADOCK 05000251
Q PDC

IE11

cc: Stewart D. Ebnetter, Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

-A064-
1/0