

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9003200397 DOC.DATE: 90/03/08 NOTARIZED: NO DOCKET #  
 FACIL:50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250  
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251  
 AUTH.NAME AUTHOR AFFILIATION  
 HARRIS,K.N. Florida Power & Light Co.  
 RECIP.NAME RECIPIENT AFFILIATION  
 Document Control Branch (Document Control Desk)

SUBJECT: Mofidies interim commitment to have physical barriers installed as stated, per IRs 50-250/81-01 & 251/81-01.

DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2  
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

### NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD2-2 PD	1 1	EDISON, G	1 1
INTERNAL: AEOD	1 1	AEOD/DEIIB	1 1
AEOD/TPAD	1 1	DEDRO	1 1
NRR SHANKMAN, S	1 1	NRR/DLPQ/LPEB10	1 1
NRR/DOEA DIR 11	1 1	NRR/DREP/PEPB9D	1 1
NRR/DREP/PRPB11	2 2	NRR/DRIS/DIR	1 1
NRR/DST/DIR 8E2	1 1	NRR/PMAS/ILRB12	1 1
NUDOCS-ABSTRACT	1 1	OGC/HDS2	1 1
REG FILE 02	1 1	RES MORISSEAU, D	1 1
RGN2 FILE 01	1 1		
EXTERNAL: LPDR	1 1	NRC PDR	1 1
NSIC	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 23 ENCL 23

R  
I  
D  
S  
/  
A  
D  
D  
S  
  
R  
I  
D  
S  
/  
A  
D  
D  
S





FPL

MAR 08 1990

L-90-35

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4  
Docket Nos. 50-250 and 50-251  
Modification of Commitment  
Inspection Report 81-1

Florida Power & Light Company (FPL) is modifying an interim commitment to have physical barriers installed at appropriate openings in the surveillance area boundaries in the Control Room.. This commitment was made as a short-term corrective action in FPL's response (L-81-174, dated April 20, 1981) to a Notice of Violation dated February 18, 1981, based on findings identified in NRC Inspection Report 250, 251/81-01.

Long term corrective action resulted in physical changes to the Control Room which enhance operator awareness of the surveillance area, and serve to limit access to this area by non-licensed personnel. These changes include the following:

1. Modification of the Plant Supervisor's - Nuclear office to overlook the Control Panels.
2. Human Factors Engineering Study of the Control Room.
3. Lines on the floor designate the "at-the-controls" area boundaries.

9003200397 900308  
PDR ADDCK 05000250  
Q PDC

*Handwritten:* 110

L-90-35

Page 2

In addition, a definite improvement in operator professionalism in the Control Room was observed and commented on by the Management on Shift (MOS) personnel. This observation further assures adherence to surveillance area boundaries. Based on these modifications and observations, the barriers are no longer necessary and will be removed.

Very truly yours,



K. N. Harris  
Site Vice President

KNH/JRH/rat

attachment

cc: Stewart D. Ebnetter, Regional Administrator, Region II, USNRC  
Senior Resident Inspector, USNRC, Turkey Point Plant

