

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9010240158 DOC. DATE: 90/10/15 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH. NAME AUTHOR AFFILIATION
 GOLDBERG, J.H. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 EBNETER, S.D. Region 2 (Post 820201)

SUBJECT: Responds to SALP Insp Repts 50-250/90-26 & 50-251/90-26, per NRC 900925 ltr.

DISTRIBUTION CODE: IE40D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: Systematic Assessment of Licensee Performance (SALP) Report

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 LA	1 0	PD2-2 PD	1 1
	EDISON, G	1 1		
INTERNAL:	AEOD/DOA	1 1	AEOD/DSP/TPAB	1 1
	COMMISSION	5 5	DEDRO	1 1
	NRR SHANKMAN, S	1 1	NRR/DLPQ/LHFB11	1 1
	NRR/DLPQ/LPEB10	1 1	NRR/DOEA/OEAB11	1 1
	NRR/DREP/PEPB9D	1 1	NRR/DREP/PRPB11	1 1
	NRR/DRIS/RSGB9D	1 1	NRR/DRIS/RSIB9A	1 1
	NRR/PMAS/ILRB12	1 1	NUDOCS-ABSTRACT	1 1
	OE DFR	1 1	OGC/HDS2	1 1
	<u>REG FILE</u> 02	1 1	RGN2 FILE 01	1 1
EXTERNAL:	L ST LOBBY WARD	1 1	NRC PDR	1 1
	NSIC	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 28 ENCL 27 0





OCTOBER 15 1990

L-90-369

Mr. Stewart D. Ebnetter
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
101 Marietta Street, N. W., Suite 2900
Atlanta, GA 30323

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Inspection Report No. 90-26
Response to Systematic Assessment of Licensee Performance

Dear Mr. Ebnetter:

By letter dated September 25, 1990, the NRC provided to Florida Power and Light Company (FPL) the Systematic Assessment of Licensee Performance (SALP) Report. The evaluation summarized by this report covers the period from August 1, 1989, through July 31, 1990. FPL has reviewed this report and believes that it is a comprehensive and fair assessment of Turkey Point's performance.

We are pleased that our efforts at Turkey Point have resulted in visible improvement. Though progress has been made at Turkey Point, areas for additional improvement remain. The SALP Report identifies improvement opportunities and challenges in each SALP category. We will continue our program to pursue improvement in operation and maintenance activities at Turkey Point and in so doing be responsive to the identified NRC concerns.

Very truly yours,

J. H. Goldberg
President
Nuclear Division

JHG/GS

cc: Document Control Desk, USNRC, Washington, D.C.
Dr. Thomas E. Murley, Director, Office of Nuclear Reactor
Regulation, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

9010240158 901015
PDR ADOCK 05000250
PDC

IE40
1/0

11-22



ENCLOSURE 4

ERRATA SHEETS

<u>Page</u>	<u>Line</u>	<u>Initial Report Reads</u>	<u>Final Report Reads</u>
Coversheet	2	Initial SALP Board Report	Final SALP Report

ENCLOSURE

INITIAL SALP BOARD REPORT

U. S. NUCLEAR REGULATORY COMMISSION

REGION II

SYSTEMATIC ASSESSMENT OF LICENSEE PERFORMANCE

INSPECTION REPORT NUMBER

50-250/90-26 AND 50-251/90-26

FLORIDA POWER AND LIGHT

TURKEY POINT UNITS 3 AND 4

AUGUST 1, 1989 - JULY 31, 1990

ENCLOSURE

FINAL SALP REPORT

U. S. NUCLEAR REGULATORY COMMISSION

REGION II

SYSTEMATIC ASSESSMENT OF LICENSEE PERFORMANCE

INSPECTION REPORT NUMBER

50-250/90-26 AND 50-251/90-26

FLORIDA POWER AND LIGHT

TURKEY POINT UNITS 3 AND 4

AUGUST 1, 1989 - JULY 31, 1990