

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9211100373 DOC. DATE: 92/11/05 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH. NAME PLUNKETT, T.F. AUTHOR AFFILIATION Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION Document Control Branch (Document Control Desk)

SUBJECT: Forwards "Fifteenth Year Tendon Surveillance Supplemental Rept," in response to discrepancy discovered during review of fifteenth year data in preparation for twentieth year tendon surveillance, per util 880804 ltr.

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1417
 TITLE: OR Submittal: General Distribution

NOTES: NRR RAGHAVAN, L 05000250/
 NRR RAGHAVAN, L 05000251

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD2-2 LA	1 1	PD2-2 PD	1 1
AULUCK, R	2 2		
INTERNAL: NRR/DET/ESGB	1 1	NRR/DOEA/OTSB11	1 1
NRR/DST/SELB 7E	1 1	NRR/DST/SICB8H7	1 1
NRR/DST/SRXB 8E	1 1	NUDOCS-ABSTRACT	1 1
OC/LFMB	1 0	OGC/HDS3	1 0
REG FILE 01	1 1	RES/DSIR/EIB	1 1
EXTERNAL: NRC PDR	1 1	NSIC	1 1
NOTES:	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK. ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 17 ENCL 15

MA



NOV 05 1992

L-92-287

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4
Docket No. 50-250 and 50-251
Fifteenth Year Tendon Surveillance
Supplemental Report

By letter L-88-336 dated August 4, 1988, Florida Power and Light Company (FPL) transmitted a special report summarizing the low lift-off values of hoop tendons for Turkey Point Unit 4. While reviewing the fifteenth year data in preparation for the twentieth year tendon surveillance, FPL discovered differences between the then proposed and now approved Regulatory Guide requirements. In response to this discrepancy, a revision to the Fifteenth Year Tendon Surveillance Report for Turkey Point Units 3 and 4 is enclosed.

Should there be any questions, please contact us.

Very truly yours,

T. F. Plunkett
Vice President
Turkey Point Nuclear

TFP/RJT/rt

Enclosure

cc: S. B. Ebnetter, Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

1000008

9211100373 921105
PDR ADOCK 05000250
P PDR

ADD 1

