

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9411010357 DOC. DATE: 94/10/26 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251

AUTH. NAME AUTHOR AFFILIATION
 PLUNKETT, T.F. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards "COLR for Turkey Point Units 3 & 4."

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+9
 TITLE: OR Submittal: General Distribution

NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD2-2 LA	1 1	PD2-2 PD	1 1
CROTEAU, R	1 1		
INTERNAL: ELLE CENTER 01	1 1	NRR/DE/EELB	1 1
NRR/DRCH/HICB	1 1	NRR/DRPW	1 1
NRR/DSSA/SPLB	1 1	NRR/DSSA/SRXB	1 1
NUDOCS-ABSTRACT	1 1	OGC/HDS3	1 0
EXTERNAL: NOAC	1 1	NRC PDR	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL
 DESK, ROOM P1-37 (EXT. 504-2083) TO ELIMINATE YOUR NAME FROM
 DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 13 ENCL 12

MAH

P
R
I
O
R
I
T
Y

1

D
O
C
U
M
E
N
T



FPL

OCT 26 1994

L-94-268
10 CFR 50.36

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555


Gentlemen:

Re: Turkey Point Units 3 and 4
Docket No. 50-250 and 50-251
Core Operating Limits Report

By letter dated October 12, 1994, the NRC issued Amendments 167/161 to Facility Operating License No. DPR-31 and DPR-41 for Turkey Point Units 3 and 4, respectively. The amendments consisted of changes to the Technical Specifications to relocate certain cycle-specific parameter limits from the Technical Specifications to a Core Operating Limits Report (COLR). In accordance with Technical Specification 6.9.1.7, the enclosed Core Operating Limits Report is provided for Florida Power and Light Company Turkey Point Units 3 and 4. These curves are applicable for the current operating cycles of Unit 3 Cycle 14 and for Unit 4 Cycle 15 which is currently in a refueling outage.

If you have any questions, please contact us.

Very truly yours,


T. F. Plunkett
Vice President
Turkey Point Plant

TFP/RJT/rt

Attachment

cc: S. D. Ebnetter, Regional Administrator, Region II, USNRC
T. P. Johnson, Sr. Resident Inspector, USNRC, Turkey Point

010106

an FPL Group company

9411010357 941026
PDR ADDCK 05000250
P PDR

ADD1

4-1-11 4-1-11