

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9702100491 DOC. DATE: 97/02/03 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH. NAME AUTHOR AFFILIATION
 HOVEY, R.J. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards LER 96-004-03, documenting event that occurred at Turkey Point, Units 3 & 4 on 960513 until commitments made within ltr, listed.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1 + 18
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR	ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR	ENCL
PD2-3 PD	1	1	CROTEAU, R	1	1
INTERNAL: AEOD/SPD/RRAB	2	2	AEOD/SPD/RRAB	1	1
<u>FILE CENTER</u>	1	1	NRR/DE/ECGB	1	1
NRR/DE/EELB	1	1	NRR/DE/EMEB	1	1
NRR/DRCH/HHFB	1	1	NRR/DRCH/HICB	1	1
NRR/DRCH/HOLB	1	1	NRR/DRCH/HQMB	1	1
NRR/DRPM/PECB	1	1	NRR/DSSA/SPLB	1	1
NRR/DSSA/SRXB	1	1	RES/DET/EIB	1	1
RGN2 FILE 01	1	1			
EXTERNAL: L ST LOBBY WARD	1	1	LITCO BRYCE, J H	1	1
NOAC POORE, W.	1	1	NOAC QUEENER, DS	1	1
NRC PDR	1	1	NUDOCS FULL TXT	1	1

NOTE TO ALL "RIDS" RECIPIENTS:
 PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM OWFN 5D-5 (EXT. 415-2083) TO ELIMINATE YOUR NAME FROM
 DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 24 ENCL 24

ADL



FEB 3 1997

L-97-24
10 CFR 50.73

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Re: Turkey Point Units 3 & 4
Docket Nos. 50-250 & 50-251
Reportable Event: 96-004-03
Technical Specification Surveillance Procedure Review -
Identification of Inadequate Surveillance Testing


By letter L-96-068, dated March 18, 1996, as revised by L-96-115, dated May 13, 1996, Florida Power and Light Company (FPL) submitted Licensee Event Report (LER) 250/96-004-01, Inadequate Surveillance of the Auxiliary Feedwater Actuation Circuitry. This LER documented the first condition identified under the Technical Specification Surveillance Review Program in response to Generic Letter (GL) 96-01, "Testing of Safety-Related Logic Circuits."

By letter L-96-147, dated June 18, 1996, FPL submitted LER 250/96-004-02, Identification of Inadequate Surveillance Testing, to document the second condition under the Technical Specification Surveillance Review Program in response to GL 96-01, regarding inadequate surveillance of the 4KV D Bus clearing function.

The attached revised LER, 250/96-004-03, documents the third condition identified under this continuing program, regarding inadequate surveillance procedures for the main steam line isolation function. The revised LER, 250/96-04-3, is being provided in accordance with 10 CFR 50.73(a)(2)(v).

FPL will report any future event identified as a result of the GL 96-01 review as a supplement to LER 250/96-004. If there are any questions, please contact us.

Very truly yours,


R. J. Hovey
Vice President
Turkey Point Plant

CLM

attachment

cc: Luis A. Reyes, Regional Administrator, Region II, USNRC
Thomas P. Johnson, Senior Resident Inspector, Turkey Point Plant, USNRC

9702100491 970203
PDR ADOCK 05000250
S PDR

3