

# CATEGORY

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9810200272      DOC.DATE: 98/10/14      NOTARIZED: NO      DOCKET #  
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C      05000250  
 AUTH.NAME      AUTHOR AFFILIATION  
 HOVEY, R.J.      Florida Power & Light Co.  
 RECIP.NAME      RECIPIENT AFFILIATION  
 REYES, L.A.      Region 2 (Post 820201)

SUBJECT: Submits SG tube plugging 15-day rept, per TS 4.4.5.5.a. Unit 3  
 SGs inspected from 981005-08. One SG tube located in Row 42,  
 Column 55 plugged in SG 3B as result of insp.

DISTRIBUTION CODE: IE01D      COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1  
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

### NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-3 PD	1 1	JABBOUR, K	1 1
INTERNAL:	AEOD/SPD/RAB	1 1	AEOD/TTC	1 1
	DEDRO	1 1	<del>FILE CENTER</del>	1 1
	NRR/DRCH/HOHB	1 1	NRR/DRPM/PECB	1 1
	NRR/DRPM/PERB	1 1	NUDOCS-ABSTRACT	1 1
	OE DIR	1 1	OGC/HDS3	1 1
	RGN2 FILE 01	1 1		
EXTERNAL:	LITCO BRYCE, J H	1 1	NOAC	1 1
	NRC PDR	1 1	NUDOCS FULLTEXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:  
 PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS  
 OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL  
 DESK (DCD) ON EXTENSION 415-2083

TOTAL NUMBER OF COPIES REQUIRED: LTTR 17 ENCL 17

C  
A  
T  
E  
G  
O  
R  
Y  
  
1  
  
I  
C  
C  
U  
M  
U  
L  
A  
T  
E





FPL

OCT 14 1998

L-98-256  
10 CFR 50.36

Luis A. Reyes  
Regional Administrator  
U. S. Nuclear Regulatory Commission  
Atlanta Federal Center  
61 Forsyth Street, S. W., Suite 23T85  
Atlanta, GA 30303


Dear Mr. Reyes:

Re: Turkey Point Unit 3  
Docket No. 50-250  
Steam Generator Tube Plugging 15-Day Report

The Turkey Point Unit 3 steam generators were inspected from October 5, 1998 through October 8, 1998. One steam generator tube located in Row 42, Column 55 was plugged in steam generator 3B as a result of the inspection. The tube was preventatively plugged due to mechanical wear at the anti-vibration bar. No defective tubes were identified in steam generators 3A, 3B, or 3C. This letter fullfills the reporting requirements as specified in Technical Specification 4.4.5.5.a.

Should there be any questions, please contact us.

Very truly yours,

  
R. J. Hovey  
Vice President  
Turkey Point Plant

OIH

cc: USNRC, Document Control Desk, Washington, D.C.  
Senior Resident Inspector, USNRC, Turkey Point Plant

9810200272 981014  
PDR ADDCK 05000250  
G PDR

1/2  
IE 01

