

C06/20/78

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)
DISTRIBUTION FOR INCOMING MATERIAL

50-220

REC: GRIER B H'
NRC

ORG: SCHNEIDER R R
NIAGARA MOHAWK PWR

DOCDATE: 06/12/78
DATE RCVD: 06/16/78

DOCTYPE: LETTER NOTARIZED: NO

COPIES RECEIVED

SUBJECT:

LTR 1 ENCL 1

FORWARDING LICENSEE EVENT REPT (RO 50-220/78-020) ON 05/26/78 CONCERNING
DURING ROUTINE STARTUP OPERATIONS, PERFORMANCE OF SURVEILLANCE TEST
N1-1SP-RE18, FOUND RE18A WITH A SETPOINT OF 135 WC...W/ATT LERS 78-021,
78-022, 78-023.

PLANT NAME: NINE MILE PT - UNIT 1

REVIEWER INITIAL: XJM
DISTRIBUTOR INITIAL: K

***** DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS *****

INCIDENT REPORTS
(DISTRIBUTION CODE A002)

FOR ACTION: BR CHIEF ORB#3 BC**W/4 ENCL

INTERNAL:

REG FILE**W/ENCL

I & E**W/2 ENCL

I & C SYSTEMS BR**W/ENCL

NOVAK/CHECK**W/ENCL

AD FOR ENG**W/ENCL

HANAUER**W/ENCL

AD FOR OPER TECH**W/ENCL

ENGINEERING BR**W/ENCL

KREGER/J. COLLINS**W/ENCL

K SEYFRIT/IE**W/ENCL

NRC PDR**W/ENCL

MIPC**W/3 ENCL

EMERGENCY PLAN BR**W/ENCL

EEB**W/ENCL

PLANT SYSTEMS BR**W/ENCL

AD FOR PLANT SYSTEMS**W/ENCL

REACTOR SAFETY BR**W/ENCL

VOLLMER/BUNCH**W/ENCL

POWER SYS BR**W/ENCL

EXTERNAL:

LPDR'S

OSWEGO, NY**W/ENCL

TIC**W/ENCL

NSIC**W/ENCL

ACRS CAT B**W/16 ENCL

DISTRIBUTION: LTR 45 ENCL 45
SIZE: 1P+4P

CONTROL NBR: 781720026

***** THE END *****

A0/4

NRC-3031305-010

UNITED STATES NUCLEAR REGULATORY COMMISSION
DDC MONTHLY ACCESSION LIST

04/01/78 - 04/30/78

FILE LEVELS

DOC. DATE

50-366 GEORGIA POWER & LIGHT COMPANY
50 02/01/78

EDWIN I HATCH #2

ACCESSION NBR: 78041-0009

TASK NBR:

DOCUMENT TYPE: LETTER

FICHE NBR:

DOCUMENT SIZE: 1P

NOTARIZED:

DOCKET DATE:

LPDR: YES

REPORT NBR:

RECP:

RECP AFFILIA

ORG: WHITMER C F

ORG AFFILIAT

SUBJECT: FORWARDING APPLICANT'S SUMMARY & DATA
PROPOSED ETS RADIOLOGICAL ENVIRON MON

50 03/16/78

366

C

ACCESSION NBR: 78110-0101

TASK NBR:

DOCUMENT TYPE: LETTER

FICHE NBR:

DOCUMENT SIZE: 2P+16P

NOTARIZED: NO

DOCKET DATE:

LPDR: YES

REPORT NBR:

RECP: MILLER J H

RECP AFFILIA

ORG: LONG F J

ORG AFFILIAT

SUBJECT: ADVISING THAT THERE WERE NO ITEMS OF
NOS. 50-321/78-4 & 50-366/78-09 CONDU
02/27-03/03/78...W/ATT INSPEC. REPT.

50 03/17/78

366

C

ACCESSION NBR: 78083-0095

TASK NBR:

DOCUMENT TYPE: LETTER

FICHE NBR:

DOCUMENT SIZE: 1P

NOTARIZED: NO

DOCKET DATE:

LPDR: YES

REPORT NBR:

RECP: KNIGHTON G W

RECP AFFILIA

ORG:

ORG AFFILIAT

SUBJECT: ACKNOWLEDGING RECEIPT OF ENVIRON-ASSE
STATEMENT FOR SUBJECT FACILITY, AND
COMPLETED BY 04/17/78.

June 12, 1978

Mr. Boyce H. Grier
Director
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA. 19406

RE: Docket No. 50-220

Dear Mr. Grier:

In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specifications, we hereby submit the following Licensee Event Reports:

LER 78-20	which is in violation of Section 3.6.2f of the Technical Specifications
LER 78-21	which is in violation of Section 3.6.2f of the Technical Specifications
LER 78-22	which is in violation of Section 2.1.2i of the Technical Specifications
LER 78-23	in accordance with Technical Specifications

These reports were completed in the format designated in NUREG-0161, dated July 1977.

Very truly yours,

ORIGINAL SIGNED BY R.R. SCHNEIDER

R.R. Schneider
Vice President -
Electric Production

mtm

Enclosure (3 copies)

xc: Director, Office of I&E (30 copies)
Director, Office of MIPC (3 copies)

781720026

1002
4/11

1. The first step in the process is to identify the problem or issue that needs to be addressed. This involves gathering information and understanding the context of the problem.

[illegible]

100

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N Y N M P 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T

0 1 L 6 0 5 0 0 0 2 2 0 7 0 5 2 6 7 8 8 0 6 1 2 7 8 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During routine startup operations, performance of surveillance test

0 3 N1-ISP-RE18, found RE18A with a setpoint of 135 inches wc. Required

0 4 setpoint of Rx Lo-Lo-Lo water level is <= 127.1 inches wc +/- 2.6

0 5 inches wc. This condition resulted in minimal safety implications.

0 6

0 7

0 8

0 9 I B 11 E 12 E 13 I N S I T R U 14 S 15 Z 16

17 LER/RO REPORT NUMBER 7 8 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
E 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 Y 24 N 25 B 0 8 0 26
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The change in setpoint experienced on the Barton Model 288 level

1 1 indicating switch was due to instrument drift. It was reset to 126.0

1 2 inches wc. Current surveillance testing schedules are adequate to

1 3 insure early detection of future instrument drifts.

1 4

1 5 C 28 0 4 5 29 NA 30 B 31 Surveillance Testing 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION1 6 Z 33 Z 34 NA 35 NA 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE1 7 0 0 0 37 Z 38 NA 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION1 8 0 0 0 40 NA 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
PERSONNEL INJURIES NUMBER DESCRIPTION1 9 Z 42 NA 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION2 0 N 44 NA 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
PUBLICITY ISSUED DESCRIPTION

NRC USE ONLY

D.K. MacVittie

PHONE: 315-343-2110 x1558

NAME OF PREPARER



10
11
12

10
11
12

10
11
12

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	2	2	0	7	0	5	2	7	7	8	8	0	6	1	2	7	8	9
60	61	DOCKET NUMBER						68	69	EVENT DATE						74	75	REPORT DATE						80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

SYSTEM CODE I B (11)		CAUSE CODE E (12)		CAUSE SUBCODE E (13)		COMPONENT CODE I N S T R U (14)				COMP. SUBCODE S (15)		VALVE SUBCODE Z (16)	
7 8		9 10		11 12		13 14 15 16 17 18				19 20		21 22	
(17) LER/RO REPORT NUMBER		EVENT YEAR 7 8 (21) (22)		SEQUENTIAL REPORT NO. 0 2 1 (24) (25) (26)		OCCURRENCE CODE 0 3 (28) (29)		REPORT TYPE L (30)		REVISION NO. 0 (32)			
ACTION TAKEN E (33)		FUTURE ACTION Z (34)		EFFECT ON PLANT Z (35)		SHUTDOWN METHOD Z (36)		HOURS 0 0 0 0 (37) (38) (39) (40)		ATTACHMENT SUBMITTED N (41)		NPRD-4 FORM SUB. Y (42)	
(18) (19)		(20)		(21)		(22)		(23)		(24)		(25)	
PRIME COMP. SUPPLIER N (43)		COMPONENT MANUFACTURER B 0 8 0 (44) (45) (46) (47)											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

FACILITY STATUS (C) (28) % POWER (0) (6) (0) (29) NA OTHER STATUS (30) METHOD OF DISCOVERY (B) (31) DISCOVERY DESCRIPTION (32) Surveillance Testing

ACTIVITY CONTENT RELEASED OF RELEASE (Z) (33) (34) NA AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES NUMBER (1) (7) (0) (0) (0) (37) TYPE (Z) (38) DESCRIPTION (39) NA

PERSONNEL INJURIES NUMBER (1) (8) (0) (0) (0) (40) DESCRIPTION (41) NA

LOSS OF OR DAMAGE TO FACILITY TYPE (Z) (42) DESCRIPTION (43) NA

PUBLICITY ISSUED (2) (0) (N) (44) DESCRIPTION (45) NA

NRC USE ONLY

NAME OF PREPARER D.K. MacVittie

PHONE: 315-343-2110 x1558

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	2	2	0	7	0	5	2	7	7	8	8	0	6	1	2	7	8	9
60	61	DOCKET NUMBER						68	69	EVENT DATE						74	75	REPORT DATE						80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

7 8 9

0 9

SYSTEM CODE I B (11)

CAUSE CODE E (12)

CAUSE SUBCODE E (13)

COMPONENT CODE I N S T R U (14)

COMP. SUBCODE S (15)

VALVE SUBCODE Z (16)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

FACILITY STATUS									% POWER				OTHER STATUS (30)							METHOD OF DISCOVERY									DISCOVERY DESCRIPTION (32)									
C (28)									0 6 0 (29)				NA							B (31) Surveillance Testing																		

PERSONNEL EXPOSURES										
NUMBER			TYPE	DESCRIPTION (39)						
1	7	0	0	0	(37)	Z	(38)	NA		

7		8		9		11		12		80		
LOSS OF OR DAMAGE TO FACILITY										(43)		
TYPE		DESCRIPTION										
1	9	Z	(42)	NA								

7 8 9 10 80
 PUBLICITY
 ISSUED DESCRIPTION (45)
 (2) (0) (N) (44) NA
 NRC USE ONLY

NRC USE ONLY

NAME OF PREPARER

D.K. MacVittie

PHONE:

315-343-2110 x1558

917-926



26

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	N	M	P	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	LICENSEE CODE						14	LICENSE NUMBER										25	LICENSE TYPE					30	CAT		58	

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	2	2	0	7	0	5	2	6	7	8	8	0	6	1	2	7	8	9
60	61	DOCKET NUMBER								68	69	EVENT DATE					74	75	REPORT DATE					80

0 2 | During routine startup operations, LPRM response was monitored during
0 3 | control rod withdrawals. This testing found two LPRM detections (A&B)
0 4 | in LPRM string 28-33 cross connected to APRMS 11 and 15. This result-
0 5 | ed in APRM 11 having one LPRM detector input from Level B, and APRM 15
0 6 | having one input from Level A. This condition resulted in minimal
0 7 | safety implications. T.S. 3.6.2a(10) allows an APRM to be operational
0 8 | with all A and B level LPRM detector inputs bypassed.

SYSTEM CODE 0 9		CAUSE CODE I A		CAUSE SUBCODE C		COMPONENT CODE I N S T R U				COMP. SUBCODE E		VALVE SUBCODE Z	
7	8	9	10	11	12	13	14	15	16	17	18	19	20
LER/RO REPORT NUMBER 17		EVENT YEAR 7 8		SEQUENTIAL REPORT NO. 0 2 3		OCCURRENCE CODE /		REPORT TYPE L		REVISION NO. 0			
21	22	23	24	25	26	27	28	29	30	31	32		
ACTION TAKEN E		FUTURE ACTION Z		EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED N		PRIME COMP. SUPPLIER N	
33	34	35	36	37	38	39	40	41	42	43	44	COMPONENT MANUFACTURER G 0 8 0	
18	19	20	21	22	23	24	25	26	27	28	29	26	

1 0 This GE-NA-100 LPRM S/N 6610724 was replaced during the last scheduled
1 1 unit outage. During replacement, the two detectors covered by this
1 2 report were connected to the wrong APRMS. These were reconnected to
1 3 the proper APRMS, and a special instrument maintenance procedure was
1 4 generated to cover verification of cable connections.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION				
1	5	C	28	0	5	4	29	NA	C	31	Monitored LPRM responses	32
7	8	9		10	11	12	13		45	46		80

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 Z 33 Z 34 NA

7 8 9 10 11 44

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	000	(37) Z	(38) NA (39)					

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	40 NA

1		2		3		4		5		6		7		8		9		10		11		12	
LOSS OF OR DAMAGE TO FACILITY (43)																							
TYPE		DESCRIPTION																					
1	9	Z	(42)	NA																			

PUBLICITY									NRC USE ONLY
ISSUED	(44)	DESCRIPTION	(45)						
20	N	NA							

D.K. MacVittie

PHONE:

NRC USE ONLY

68 69
315-343-2110 x1558

