

**Summary of Changes to One Procedure that Implements  
the Wolf Creek Generating Station (WCGS)  
Radiological Emergency Response Plan (RERP)**

**1. Procedure EPP 06-006, "Protective Action Recommendations," Rev. 9A**

This revision of procedure EPP 06-006 corrects two typographical errors in Attachment B, "Subzones Affected by the Wind Direction." On page 3 of 63 in Attachment B, the subzone designation of "NW-1" was added as an affected subzone in the 2-5 miles column for a wind direction of 90 degrees to 270 degrees. This change corrects an omission in a previous revision of procedure EPP 06-006.

On page 9 of 63 in Attachment B, an incorrect entry of wind direction in degrees from "From 356 To 166" has been changed to the correct entry of wind direction in degrees of "From 346 To 166." These changes to procedure EPP 06-006 are minor and editorial in nature. Therefore, the changes to procedure EPP 06-006 do not decrease the effectiveness of the WCGS RERP.