

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	N	M	P	1	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	1	4			5										
7	8	9						14						15						25						26						30						57		58	
		LICENSEE CODE												LICENSE NUMBER												LICENSE TYPE															

CON'T

0	1	REPORT SOURCE										DOCKET NUMBER										EVENT DATE										REPORT DATE									
7	8	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80																			
		L	6	0	5	0	0	0	2	2	0	7	1	0	0	4	7	9	8	1	1	0	2	7	9	9															

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During steady state operation, while performing an operability test on
0 3 | #103 Diesel Generator, the associated cooling water pump tripped due to
0 4 | breaker malfunction. Before the breaker was manually closed and the
0 5 | cooling water pump restarted, the generator cooling water inlet temper-
0 6 | ature increased to 210°F. The diesels were inspected for possible
0 7 | heat damage but none was found. The cooling water pump breaker was in-
0 8 | spected and the contacts were found to be burned, and an auxiliary con-

09		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
		E	E	E		A		C	K	T	B	R	K	A	
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.					
23	24	25	26	27	28	29	30	31	32	33	34				
17		7	9	0	2	3	0	3	L	0					
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED					
35	36	37	38	39	40	41	42	43	44	45	46				
B	G	Z	Z	0	0	0	0	N	N	A	G				
18	19	20	21	22	23	24	25	26	27	28	29				

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Diesel Generator 103 cooling water pump trip was caused by breaker mal-

1 1 function. The contacts in the breaker were found to be burned and an

1 2 auxiliary contact was found stuck in the open position. The breaker was

1 3 repaired and the pump was manually started to test operability. The

1 4 cooling water pump breaker preventative maintenance procedure will be

FACILITY STATUS (28) 1 5 E 30 METHOD OF DISCOVERY (31) B Operability Test 32 DISCOVERY DESCRIPTION (32)

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 9 33 Z 34

7 8 9 10 11

AMOUNT OF ACTIVITY (35)

NA

44

45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

LOCATION OF RELEASE (36)

NA

80

PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION
1	7	000	Z	NA

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	40	NA

LOSS OF OR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION
1 9 Z (42) NA 7911130 338

2		0		ISSUED		N		DESCRIPTION		NA		PUBLICITY		45		NRC USE ONLY	
---	--	---	--	--------	--	---	--	-------------	--	----	--	-----------	--	----	--	--------------	--

NAME OF PREPARER

E. Duda

PHONE: (315) 343-2110 Ext. 1558

NRC USE ONLY

CPD 917-926

13

13

13

13

13

13

13

13

13

13

13

13

13

CONTINUED PAGE 2 LER 79-23

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	N	M	P	1	2									3								4				5
7	8	LICENSEE CODE						14	15	LICENSE NUMBER							25	26	LICENSE TYPE					30	57	CAT	58		

REPORT

REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 | tact was found stuck in the open position. The breaker was repaired
0 3 | and the pump was restarted manually to check its operation. The Diesel
0 4 | Generator Operability Test was subsequently performed and successfully
0 5 | completed. This event had minimal safety implications due to the re-
0 6 | dundancy of the system.
0 7 |
0 8 |

09		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.					
22	23	24	25	26	27	28	29	30	31	32	33	34			
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.			
35	36	37	38	39	40	41	42	43	44	45	46	47			
PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER													

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 revised to incorporate a separate operability test of the cooling water

1 1 pump prior to performing the entire diesel generator operability test.

1 2

1 3

1 4

7 8 9 80

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS (28) % POWER (29) OTHER STATUS (30) METHOD OF DISCOVERY (31) DISCOVERY DESCRIPTION (32)

1 5

ACTIVITY CONTENT
RELEASED OF RELEASE
1 6 33 34 AMOUNT OF ACTIVITY (35)
7 8 9 10 11 44
LOCATION OF RELEASE (36)
45 80

PERSONNEL EXPOSURES		DESCRIPTION	
NUMBER	TYPE		
1	7		

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	40			

[illegible]

PUBLCITY										NRC USE ONLY											
ISSUED		DESCRIPTION																			
2	0	(44)																			
7	8	9	10								68										

PHONE:

