

## (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	N	M	P	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5			
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE				30	4			57	CAT	58

**CON'T**

0	1	REPORT SOURCE										DOCKET NUMBER										EVENT DATE										REPORT DATE									
7	8	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80																			
		L	6	0	5	0	0	0	2	2	0	7	0	9	3	0	8	0	8	1	0	3	0	8	0	9															

### EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During a Safety Review and Audit Board audit it was discovered that a trip

03 | point value was not recorded on the July 21, 1979 Instrument Surveillance

04 | test for the Drywell High Pressure Trip System.

0	5
---	---

0	6
---	---

0	7	
---	---	--

0	8	
---	---	--

0 9

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

0 9 11 12 13 14 15 16

7 8 9 10 11 12 13 14 15 16 17 18 19 20

(17) LER/RO REPORT NUMBER	EVENT YEAR			SEQUENTIAL REPORT NO.			OCCURRENCE CODE		REPORT TYPE			REVISION NO.	
	8	0	—	0	2	4	/	0	3	L	—	0	
	21	22	23	24	25	26	27	28	29	30	31	32	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.	
H	(18) G	(19)	Z	(20)	Z	(21)	0	0	0	(22)	N	(23)	N
33	34	35	36	37	38	39	40	41	42	43	44	45	46
PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER											
N		(25)	R	3	6	9							
47		48		49		50		51		52		53	

### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | SEE OVER

[illegible]

1	2	
---	---	--

1	3	
---	---	--

1	4	
---	---	--

FACILITY STATUS		% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)							
1	5	E	28	0	9	7	29	N/A	B	31	SRAB AUDIT	32

RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51

N/A

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	N/A	

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
0	0	0	(40) N/A

		LOSS OF OR DAMAGE TO FACILITY		(43)
TYPE		DESCRIPTION		
1	9	Z	(42) N/A	

8 9 10  
PUBLCITY  
ISSUED: (45) DESCRIPTION: 8 011070 381  
2 0 4 4 N/A  
7 8 9 10 60 60 80  
NRC USE ONLY

**NRC USE ONLY**

8 011070381

Paul Harrison

BUONE. (315) 343-2110, X1212

#### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

This is attributed to an oversight in data recording by the technician performing the test. Satisfactory test performance was indicated on data sheet checkoffs. Tests performed previous to and following the oversight indicate a satisfactory trip point setting. Other switches performing a redundant function were found with satisfactory test data. The importance of making sure all test data is complete was reviewed with testing personnel. In the future two levels of review will be performed by the Instrument and Control department.