

June 26, 1978
L-78-219

Central File
50-389

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
230 Peachtree Street, N. W., Suite 1217
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:JPO
50-389

Florida Power and Light Company has reviewed IE bulletin 78-05 concerning G. E. Model CR 105X auxiliary contact mechanism malfunction in 480 volt motor starters and contactors.

Florida Power and Light has requested from all suppliers of electrical equipment with a potential for use of the GE CR105X auxiliary contact mechanisms a response in writing concerning its use. Should these contacts be found in equipment to be supplied to St. Lucie Unit 2, the contacts will either be replaced or modified in accordance with the GE service letter.

The results of this investigation will be available by September 1, 1978.

Very truly yours,

Robert E. Uhrig

Robert E. Uhrig
Vice President

REU:MV:s1

cc: Harold F. Reis, Esquire

Ad 2
BD