

50-315

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO:

Mr. J. G. Keppler

FROM:

Indiana & Michigan Power Company
Bridgman, Michigan
R. W. Jurgensen

DATE OF DOCUMENT

4/19/77

DATE RECEIVED

4/22/77

☒ LETTER☐ NOTORIZED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

☐ ORIGINAL
☒ COPY☒ UNCLASSIFIED

100

DESCRIPTION

Ltr. trans the following:

DO NOT REMOVE

(1-P)

PLANT NAME:

Cook Unit No. 1

RJL

ACKNOWLEDGED

ENCLOSURE

Licensee Event Report (RO 50-315/77-17) on
4/3/77 concerning the 50 foot wind direction
recorder being discovered inoperable....

(1-P)

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION

BRANCH CHIEF:

W/3 CYS FOR ACTION

LIC, ASST.:

W/1 CYS

ACRS 10 CYS HOLDING/SENT

Ziemann

Diggs

AS CATB

INTERNAL DISTRIBUTION

☒ REG FILE

NRC PDR

I & E (2)

MIPC

SCHROEDER/IPPOLITO

HOUSTON

NOVAK/CHECK

GRIMES

CASE

BUTLER

HANAUER

TEDESCO/MACCARY

EISENHUT

BAER

SHAO

VOLLMER/BUNCH

KREGER/J. COLLINS

EXTERNAL DISTRIBUTION

LPDR: St Joseph, MI

TIC:

NSIC:

CONTROL NUMBER

771130004 AO 4
60

1944-1945


1944-1945





INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106



April 19, 1977

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

REGULATORY DOCKET FILE COPY


Operating License DPR-58
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of Appendix A Technical Specifications and the United States Nuclear Regulatory Commission Regulatory Guide 1.16, Revision 4, Section 2.b, the following report is submitted:

RO 50-315/77-17.

Sincerely,


for R.W. Jurgensen
Plant Manager

/bab

cc: R.S. Hunter
J.E. Dolan
G.E. Lien
R. Kilburn
R.J. Vollen BPI
R.C. Callen MPSC
K.R. Baker RO:III
P.W. Steketee, Esq.
R. Walsh, Esq.
G. Charnoff, Esq.
G. Olson
J.M. Hennigan
PNSRC
R.S. Keith
Dir., IE (30 copies)
Dir., MIPC (3 copies)

771130004

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME														LICENSE NUMBER												LICENSE TYPE				EVENT TYPE	
01	M	I	D	C	C	1	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	3							
7	8	9				14	15											25	26			30	31	32							
01		CONT		CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER				EVENT DATE				REPORT DATE													
01						L	L	0	5	0	-	0	3	1	5	0	4	0	3	7	7	0	4	1	9	7	7				
7	8			57	58	59	60	61					68	69			74	75									80				

EVENT DESCRIPTION

02	WHILE IN MODE 1, AT 98% POWER, THE 50 FOOT WIND DIRECTION RECORDER WAS DISCOVERED																								80
03	INOPERABLE ON 4/3/77. THE PROBLEM WAS IDENTIFIED AS A BROKEN RECORDER DRIVE CABLE.																								80
04	A NEW DRIVE CABLE WAS INSTALLED AND THE SYSTEM DECLARED OPERABLE IN COMPLIANCE WITH																								80
05	TECHNICAL SPECIFICATION #3.3.3.4 ON 4/4/77.																								80
06																									80
	(R0-50-315/77-17)																								80

SYSTEM CODE				CAUSE CODE		COMPONENT CODE				PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
07	I	E	E	I	N	S	T	R	U	L	X	9	9	9	N		
7	8	9	10	11	12				17	43	44			47	48		

CAUSE DESCRIPTION

08	CAUSE OF THE EVENT WAS THE BROKEN DRIVE CABLE WHICH FAILED DURING NORMAL OPERATION.																								80
09	PERSONNEL PERFORMING RECORDER MAINTENANCE WERE INSTRUCTED TO ADD THE RECORDER DRIVE																								80
10	UNITS TO THEIR ROUTINE INSPECTIONS.																								80

FACILITY STATUS				% POWER				OTHER STATUS				METHOD OF DISCOVERY		DISCOVERY DESCRIPTION			
11	E	0	9	8	NA	B	ROUTINE SURVEILLANCE										
7	8	9	10	11	12	13	44	45	46						80		

FORM OF ACTIVITY RELEASED				CONTENT OF RELEASE				AMOUNT OF ACTIVITY				LOCATION OF RELEASE			
12	Z	Z	NA	NA											
7	8	9	10	11	12	13	44	45							80

PERSONNEL EXPOSURES

NUMBER				TYPE		DESCRIPTION									
13	0	0	0	Z	NA										
7	8	9	11	12	13										80

PERSONNEL INJURIES

NUMBER				DESCRIPTION											
14	0	0	0	NA											
7	8	9	11	12											80

OFFSITE CONSEQUENCES

15	NA																								80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE				DESCRIPTION											
16	Z	NA													
7	8	9	10												80

PUBLICITY

17	NA																								80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	NA																								80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19	NA																								80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

NAME: TERRY BEILMAN

PHONE: (616) 465-5901 (368)

