

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO:

Mr. J. G. Keppler

FROM:

Indiana & Michigan Power Co.
Bridgman, Michigan
R. W. Jurgensen

DATE OF DOCUMENT

1/14/77

DATE RECEIVED

1/25/77

☒ LETTER
☒ ORIGINAL
☐ COPY☐ NOTORIZED
☒ UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

One signed

DESCRIPTION

Ltr. trans the following:

PLANT NAME:

Cook Unit No. 1

(1-P) (2-P)

ENCLOSURE

Licensee Event Report (RO 50-315/76-57) on 12/17/76 concerning the motor operated suction valve being found in the closed position when performing a normal valve lineup check prior to starting the west containment spray pump for a special test run...

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION 1/31/77

RJL

☒ BRANCH CHIEF: Ziemann
☒ W/3 CYS FOR ACTION
☒ LIC. ASST.: Diggs
☒ W/ CYS
☒ ACRS 16 CYS HOLDING/SENT: (AT.B. (1/31/77))
☒ Benedict

INTERNAL DISTRIBUTION

☒ REG FILE
☒ NRC PDR
☒ I & E (2)
☒ MIPC
☒ SCHROEDER/IPPOLITO
☒ HOUSTON
☒ NOVAK/CHECK
☒ GRIMES
☒ CASE
☒ BUTLER
☒ HANAUER
☒ TEDESCO/MACCARY
☒ EISENHUT
☒ BAER
☒ SHAO
☒ VOLLMER/BUNCH
☒ KREGER/J. COLLINS

DO NOT REMOVE
ACKNOWLEDGED

EXTERNAL DISTRIBUTION

CONTROL NUMBER

☒ LPDR: St. Joseph, Mich.
☒ TIC:
☒ NSIC:

864

GPO



12

() ()





INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

Regulatory Docket File

D. Lannan

January 14, 1977

Mr. J. G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137



Operating License DPR-58
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of Appendix A Technical Specifications and the United States Nuclear Regulatory Commission Regulatory Guide 1.16, Revision 4, Section 2.b, the following report is submitted:


RO 50-315/76-57

Sincerely,

R. W. Jurgensen
R. W. Jurgensen
Plant Manager

RWJ/mj

cc: R. S. Hunter
J. E. Dolan
G. E. Lien
R. Kilburn
R. J. Vollen BPI
R. C. Callen MPSC
K. R. Baker RO: III
R. Walsh, Esq.
P. W. Steketee, Esq.
G. Charnoff, Esq.
G. Olson
J. M. Hennigan
PNSRC
R. W. Keith
Dir., IE (30 copies)
Dir., MIPC (3 copies)



864

JAN 17 1977



[PLEASE PRINT ALL REQUIRED INFORMATION]

01		CONT		CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER								EVENT DATE						REPORT DATE					
7	8	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80				
				L	L	0	5	0	-	0	3	1	5	1	2	1	7	7	6	0	1	1	4	7	7				

012 WHEN PERFORMING A NORMAL VALVE LINEUP CHECK PRIOR TO STARTING THE WEST CONTAINMENT
7 8 9 80
013 SPARY PUMP FOR A SPECIAL TEST RUN THE MOTOR OPERATED SUCTION VALVE WAS FOUND IN THE
7 8 9 80
014 CLOSED POSITION. IT IS BELIEVED THAT THIS VALVE WAS INADVERTANTLY LEFT IN THE
7 8 9 80
015 CLOSED POSITION WHEN THE VALVE WAS OPERATED AS PART OF SURVEILLANCE TESTING
7 8 9 80
016 CONDUCTED THE PREVIOUS DAY. IT IS ESTIMATED (SEE SUPPLEMENT) (LER RO-50-315/76-57)
7 8 9 80

SYSTEM CODE		CAUSE CODE	COMPONENT CODE					PRIVATE COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOLATION			
07	S B	A	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z	N			
7	8	9	10	11	12	13	14	15	16	17	43	44	45	46	47	48

08 THE STEP IN THE SURVEILLANCE PROCEDURE REQUIRING THE VALVE TO BE OPENED HAD BEEN
7 8 9 80
09 SIGNED OFF AS BEING COMPLETED. HOWEVER, THE MOST LIKELY REASON FOR THE VALVE BEING
7 8 9 80
10 IN THE CLOSED POSITION IS THAT IT WAS LEFT IN THIS POSITION (SEE SUPPLEMENT).
7 8 9 80

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION		
11	E	0	9	5	N.A.	I	CONDUCTING SPECIAL TEST			
7	8	9	10	11	12	13	44	45	46	80

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
<u>1</u>	<u>2</u>	<u>Z</u>		N.A.		N.A.	
7	8	9	10	11	44	45	80

NUMBER			TYPE	DESCRIPTION
13	000	Z	N.A.	

NUMBER				DESCRIPTION
14	0	0	0	N.A.

15 NONE: SINCE THE REDUNDANT CONTAINMENT SPRAY SYSTEM WAS OPERABLE. (SEE SUPPLEMENT)

TYPE			DESCRIPTION
16	Z		N.A.

17 7 8 9 80

18 THE IMPORTANCE OF VARIFYING THAT ALL VALVES ARE LEFT IN THEIR CORRECT POSITIONS HAS

19 | BEEN STRONGLY STRESSED TO ALL OPERATING PERSONNEL. (SEE SUPPLEMENT)

NAME: Alfred Anderson PHONE: 616 465-5901



10-11-68

10-11-68

10-11-68

EVENT DESCRIPTION

THAT THE MAXIMUM TIME THE VALVE COULD HAVE BEEN IN THE CLOSED POSITION IS 30 HOURS.

CAUSE DESCRIPTION

FROM THE SURVEILLANCE TEST.

PROBABLE CONSEQUENCES

ALSO, TECHNICAL SPECIFICATION 3.6.2.1 PERMITS ONE CONTAINMENT SPRAY SYSTEM TO BE INOPERABLE FOR 72 HOURS.

ADDITIONAL FACTORS

THE STATUS LIGHTS WHICH ARE DESIGNED TO INDICATE PROPER VALVE LINEUP DURING SPRAY ACTUATION CONDITIONS WILL BE MARKED SO THAT THE OPERATOR CAN READILY DETERMINE IF THE VALVE IS IN ITS PROPER POSITION DURING NORMAL OPERATION.



Handwritten scribbles or marks in the top right corner.

Faint, illegible handwritten text or markings at the bottom of the page.