

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

5. 50117

6
6/4/76

Incident Notification From: Indiana & Michigan Power Co. 50-315
(Licensee & Docket No. (or License No.))

Transmittal Date: June 4, 1976 D. C. Cook Plant Unit 1

Distribution:

IE Chief, FOSB
IE Chief, FC&EB
IE:HQ(4)
Licensing(4)
DR Central Files
IE Files

Distribution:

IE Chief, FOSB
IE Chief, FC&EB
IE:HQ(4)
L:D/D for Fuels & Materials
DR Central Files
IE Files





INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

April 23, 1976

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-58
Docket No. 50-315


Dear Mr. Keppler:

This is to confirm our verbal report to NRC RO: III Inspector, Mr. K.R. Baker, of April 22, 1976. At that time we reported that auxiliary feed water valve FMO-211 was found to be installed with flow in the wrong direction.

A review of the consequences of this condition indicated that there were no adverse effects to the public health and safety.

We are continuing our investigation and will submit a formal report by May 6, 1976, as required by Nuclear Regulatory Commission Regulatory Guide 1.16, Revision 4, Section 2.a.

Sincerely,


R.W. Jorgensen
Plant Manager

/bab

cc: R.S. Hunter	J.M. Hennigan
J.E. Dolan	PNSRC
G.E. Lien	R.S. Keith
R. Kilburn	Dir., IE (40 copies)
R.J. Vollen BPI	Dir., MIPC (4 copies)
R.C. Callen MPSC	
K.R. Baker RO:III	
P.W. Steketee, Esq.	
R. Walsh, Esq.	
G. Charnoff, Esq.	
G. Olson	

APR 26 1976