

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

6
2/4/76

Incident Notification From: Indiana & Michigan Power Company 50-315
(Licensee & Docket No. (or License No.))

Transmittal Date: June 4, 1976 D. C. Cook Unit #1

Distribution:

IE Chief, FOSB
IE Chief, FC&EB
IE:HQ(4)
Licensing(4)
DR Central Files
IE Files

Distribution:

IE Chief, FOSB
IE Chief, FC&EB
IE:HQ(4)
L:D/D for Fuels & Materials
DR Central Files
IE Files



INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49108

April 19, 1976

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-58
Docket No. 50-315


Dear Mr. Keppler:

This is to confirm our verbal report to NRC RO: III Inspector, Mr. K.R. Baker, of April 16, 1976, in which we reported we had a potential problem of inoperable hydraulic snubbers in safety related systems.

Our investigation since April 16, 1976, reveals that we did in fact have inoperable hydraulic snubbers in safety related systems.

We are continuing this investigation and will submit a formal report by May 3, 1976, as required by Nuclear Regulatory Commission Regulatory Guide 1.16, Revision 4, Section 2.a.

Sincerely;


R.W. Jorgensen
Plant Manager

/bab

cc: R.S. Hunter	PNSRC
J.E. Dolan	R.S. Keith
G.E. Lien	Dir., IE (40 copies)
R. Kilburn	Dir., MIPC (4 copies)
R.J. Vollen BPI	
R.C. Callen MPSC	
K.R. Baker RO: III	
P.W. Steketee, Esq.	
R. Walsh, Esq.	
G. Charnoff, Esq.	
G. Olson	

Rec'd 4/19/76 - 4:09 J.L.

