

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 13633

FILE: INCIDENT REPORT FI

FROM: Indiana & Michigan Power Co. Bridgman, Mich. 49106 R.W. Jurgensen			DATE OF DOC 12-3-75	DATE REC'D 12-5-75	LTR XX	TWX	RPT	OTHER
TO: Mr. J.G. Keppler			ORIG	CC 30	OTHER	SENT AEC PDR XX SENT LOCAL PDR XX		
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 30		DOCKET NO: 50-315		

DESCRIPTION: Ltr trans the following:

ENCLOSURES: Licensee Event Report AO-50-315/75-73 on 11-13-75 re missing tail assembly & bent arrow shaft on the wind speed & direction recorder.

(30 cys encl rec'd)

ACKNOWLEDGED

Do Not Remove

PLANT NAME: Donald C. Cook Unit 1

FOR ACTION/INFORMATION

DHL 12-6-75

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
✓ KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	REID W/ Copies

INTERNAL DISTRIBUTION

REG FILE NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE	TECH REVIEW SCHROEDER MACCARY KNIGHT PAWLICKI SHAO **STELLO **HOUSTON **NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER	DENTON **GRIMES GAMMILL KASTNER BALLARD SPANGLER ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	LIC ASST R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. RUSHBROOK (L) S. REED (E) ✓ M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L) M. DUNCAN (E)	A/T IND. BRAITMAN SALTZMAN MELTZ PLANS MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
---	--	--	--	--

EXTERNAL DISTRIBUTION

1 - LOCAL PDR St. Joseph, Mich.
1 - TIC (ABERNATHY) (1)(2)(10)
1 - NSIC (BUCHANAN)
1 - ASLB
1 - Newton Anderson
16 ACRS SENT TO LIC ASST M. Service 12-6-75
** SEND ONLY TEN DAY REPORTS

1 - NATIONAL LABS
1 - W. PENNINGTON, Rm E-201 GT
1 - CONSULTANTS
NEWMARK/BLUME/AGBABIAN

1 - PDR-SAN/LA/NY
1 - BROOKHAVEN NAT LAB
1 - G. ULRIKSON, ORNL
1 - AGMED (RUTH GUSSMAN)
Rm B-127 GT
1 - J. D. RUNKLES, Rm E-201 GT

12

12

12

12

12

12

12

12

12

12

12

12

12

12

12



INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

Regulatory Docket File

December 3, 1975



Mr. J.G. Keppler; Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137


Operating License DPR-58
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of Appendix A Technical Specifications and the United States Nuclear Regulatory Commission Regulatory Guide 1.16, Revision 3, Section 2.b, the following Abnormal Occurrence Report is submitted:


A0 50-315/75-73

Sincerely,


R.W. Jurgensen
Plant Manager

/bab

cc: R.S. Hunter
J.E. Dolan
G.E. Lien
R.J. Vollen BPI
R. Kilburn
R.C. Callen MPSC
K.R. Baker RO: III
P.W. Steketee, Esq.
R. Walsh, Esq.
G. Charnoff, Esq.
G. Olson
PNSRC
R.S. Keith
Director, IE (30 copies)
Director, MIPC (3 copies)



13633

11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100



LICENSEE EVENT REPORT

Regulatory Docket File

CONTROL BLOCK:

(2) PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: 01 M I D I C I 1
 LICENSE NUMBER: 00-000000-000
 LICENSE TYPE: 411111
 EVENT TYPE: 01
 CATEGORY: 01 CONT
 REPORT TYPE: P10
 REPORT SOURCE: L
 DOCKET NUMBER: 050-0315
 EVENT DATE: 1111375
 REPORT DATE: 1112475

EVENT DESCRIPTION

02 WHILE IN MODE 3, THE WIND SPEED AND DIRECTION RECORDER
03 FOR THE 150 FOOT MICROWAVE LOCATION BECAME INOPERABLE.
04 INVESTIGATION FOUND MISSING TAIL ASSEMBLY AND BENT
05 LARROW SHAFT. SHAFT AND TAIL ASSEMBLY WERE REPLACED AND
06 SYSTEM RETURNED TO OPERATION (AO-50-315/75-73)

SYSTEM CODE		CAUSE CODE		COMPONENT CODE						PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
07	IE	C		I	N	S	T	R	U		O	Z	Z	Z	Z	N	
7	8	9	10							11	12	13	14	15	16	17	
											43	44	45	46	47	48	

CAUSE DESCRIPTION

08 THE APPARENT CAUSE OF THE MALFUNCTION WAS THE ASSEM-
7 8 9 80
09 BLY BEING STRUCK BY A BIRD AS EVIDENCED BY THE
7 8 9 80
10 PRESENCE OF BLOOD AND FEATHERS ON THE TOWER
7 8 9 80

FACILITY STATUS		% POWER	OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	G	000	NA		B	ROUTINE INSPECTION		
7	8	9	10	12	13	44	45	46
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE		
12	Z	Z	NA		NA			
7	8	9	10	11	44	45		80

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
13	0	0	0	Z	NA

PERSONNEL INJURIES

NUMBER				DESCRIPTION	
1	4	0	0	0	NA

OFFSITE CONSEQUENCES

15 NONE - NO GASEOUS RELEASES MADE

LOSS OR DAMAGE TO FACILITY

				TYPE	DESCRIPTION
16	7	8	9	7	NA

PUBLICITY

17 NA

ADDITIONAL FACTORS

18 NA

19 INA

NAME: G. SWAN

PHONE: 465-5901(368)

