

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORTTO:
Mr. Norman C. Moseley
FROM:
Tennessee Valley Authority
Chattanooga, Tennessee
H. S. FoxDATE OF DOCUMENT
11/10/76DATE RECEIVED
11/16/76☒ LETTER
☐ ORIGINAL
☒ COPY
☐ NOTORIZED
☒ UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED
None signed

DESCRIPTION

Ltr. trans the following:

ACKNOWLEDGED
DO NOT REMOVE

(1-P)

PLANT NAME:

Browns Ferry #2

ENCLOSURE

Licensee Event Report (RO 50-260//7614) on
10/12/76 concerning control room annunciator
2-XA-55-8E that failed.

(1-P)

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION 11/16/76

RJL

☒ BRANCH CHIEF: Schwencer
☒ W/3 CYS FOR ACTION
☒ LIC. ASST.: Sheppard
☒ W/ CYS
☒ ACRS/6 CYS HOLDING/SENT TO EA (at B. (11/16/76))

INTERNAL DISTRIBUTION

☒ REG. FILE
☒ NRC PDR
☒ I & E (2)
☒ MIPC
☒ SCHROEDER/IPPOLITO
☒ HOUSTON
☒ NOVAK/CHECK
☒ GRIMES
☒ CASE
☒ BUTLER
☒ HANAUER
☒ TEDESCO/MACCARY
☒ EISENHUT
☒ BAER
☒ SHAO
☒ VOLLMER/BUNCH
☒ KREGER/J. COLLINS

EXTERNAL DISTRIBUTION

☒ LPDR: Athens, Ala.
☒ TIC:
☒ NSIC:

CONTROL NUMBER

11661

ACKNOWLEDGED

DO NOT WRITE



TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

November 10, 1976

Regulatory Docket File

Mr. Norman C. Moseley, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
230 Peachtree Street, NW., 8th Floor
Atlanta, Georgia 30303



Dear Mr. Moseley:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 -
DOCKET NO. 50-260 - FACILITY OPERATING LICENSE DPR-52 - REPORTABLE
OCCURRENCE REPORT BFRO-50-260/7614

The enclosed report is to provide details concerning control room annunciator 2-XA-55-8E that failed. This report is submitted in accordance with Browns Ferry Technical Specifications Section 6. This event occurred on Browns Ferry Nuclear Plant unit 2.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. S. Fox
Director of Power Production

Enclosure (3)


CC (Enclosure):

Director (3)

Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director (40)

Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555



11601

Regulatory Docket File



LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSE NAME					LICENSE NUMBER										LICENSE TYPE					EVENT TYPE					
0	1	A	L	B	R	F	2	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	3
7	8	9					14	15										25	26				30	31	32

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER						EVENT DATE						REPORT DATE								
0	1		L	L	0	5	0	-	0	2	6	0	1	0	1	2	7	6						
7	8	57	58	59	60	61						68	69					74	75					80

EVENT DESCRIPTION

02	Control room annunciator 2-XA-55-8E failed. This annunciator is for smoke and heat	80
03	alarms in the fire protection system.	80
04		80
05		80
06		80
07		80

PRIME

SYSTEM CODE				CAUSE CODE	COMPONENT CODE						COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOLATION		
7	8	9	10	11	12							43	44					48
5	7	A	B	E	A	N	N	U	N	d		L	L	2	9	5		N

CAUSE DESCRIPTION

09	The power supply card failed, Lundell Controls part number 310948 in the Statalarm	80
09	annunciator. (BFRO-50-260/7614)	80
10		80
		80

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	B	0	5	9	N/A	A		N/A	
7	8	9	10	12	13	44	45	46	80
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY				LOCATION OF RELEASE	
12	3	3			N/A			N/A	
7	8	9	10	11	44	45			80

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
13	0	0	0	2	N/A

PERSONNEL INJURIES

NUMBER			DESCRIPTION
14	0	0	N/A

OFFSITE CONSEQUENCES

15	N/A	80
----	-----	----

LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION
15 8	N/A

PUBLICITY

17	N/A	80
----	-----	----

ADDITIONAL FACTORS

18	Replaced power supply card and returned annunciator to normal	80
19		80

NAME: _____ PHONE: _____

PHONE:

GPO 831-667



TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

November 10, 1976

Mr. Norman C. Moseley, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
230 Peachtree Street, NW., 8th Floor
Atlanta, Georgia 30303

Dear Mr. Moseley:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 -
DOCKET NO. 50-260 - FACILITY OPERATING LICENSE DPR-52 - REPORTABLE
OCCURRENCE REPORT BFRO-50-260/7614

The enclosed report is to provide details concerning control room annunciator 2-XA-55-8E that failed. This report is submitted in accordance with Browns Ferry Technical Specifications Section 6. This event occurred on Browns Ferry Nuclear Plant unit 2.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. S. Fox
H. S. Fox
Director of Power Production

Enclosure (3)

CC (Enclosure):

Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

50-260
A04

... ..
... ..
... ..
... ..
... ..

... ..

... ..
... ..
... ..

... ..
... ..
... ..
... ..

... ..

... ..

... ..
... ..

(1)
(2)
(3)
... ..
... ..
... ..

(4)
... ..
... ..
... ..

CENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME						LICENSE NUMBER										LICENSE TYPE				EVENT TYPE					
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
[01] A L B R F 2			0 0 - 0 0 0 0 0 0 - 0 0										4 1 1 1 1				0 3								

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER						EVENT DATE				REPORT DATE											
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
[01] CONT		[L]	[L]	0 5 0 - 0 2 6 0						1 0 1 2 7 6															

EVENT DESCRIPTION

7	8	9	[02] Control room annunciator 2-XA-55-8E failed. This annunciator is for smoke and heat																									80
7	8	9	[03] alarms in the fire protection system.																									80
7	8	9	[04]																									80
7	8	9	[05]																									80
7	8	9	[06]																									80

SYSTEM CODE			CAUSE CODE		COMPONENT CODE				PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION										
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
[02] A B			[E]		A N N U N d				[L]		L 2 9 5				[N]										

CAUSE DESCRIPTION

7	8	9	[07] The power supply card failed, Lundell Controls part number 310948 in the Statalarm																									80
7	8	9	[08] annunciator. (BFRO-50-260/7614)																									80
7	8	9	[09]																									80
7	8	9	[10]																									80

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION																	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
[11] B		0 5 9		N/A		[A]		N/A																	

FORM OF ACTIVITY RELEASE		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE																			
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
[12] Z		Z		N/A		N/A																			

PERSONNEL EXPOSURES

NUMBER			TYPE		DESCRIPTION																								
7	8	9	10	11	12	13																							
[13] 0 0 0			[Z]		N/A																								

PERSONNEL INJURIES

NUMBER			DESCRIPTION																								
7	8	9	10	11	12																						
[14] 0 0 0			N/A																								

OFFSITE CONSEQUENCES

7	8	9	[15] N/A																									80
---	---	---	----------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION																								
7	8	9	10																					80		
[16] Z		N/A																								

PUBLICITY

7	8	9	[17] N/A																									80
---	---	---	----------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

7	8	9	[18] Replaced power supply card and returned annunciator to normal																									80
7	8	9	[19]																									80

NAME: _____ PHONE: _____

