

50-260

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER

INCIDENT REPORT

TO: Mr Moseley

FROM: TVA
Chattanooga, Tn
H S Fox

DATE OF DOCUMENT

11-10-86

DATE RECEIVED

11-12-76

☒ LETTER☐ NOTORIZED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

☐ ORIGINAL
☒ COPY☒ UNCLASSIFIED

one signed

DESCRIPTION

Ltr trans the following:

PLANT NAME: Browns Ferry #2

ENCLOSURE

Licensee Event Report (RO# 7614) on
10-12-76 concerning control room annunciator
2-XA-55-8E..that failed.....ACKNOWLEDGED
DO NOT REMOVENOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J..COLLINS

FOR ACTION/INFORMATION

11-16-76 ehf

BRANCH CHIEF:

W/3 CYS FOR ACTION

LIC..ASST.:

W/1 CYS

ACRS 16 CYS HOLDING/SENT TO LA AS CAT B - 11-16-76

INTERNAL DISTRIBUTION

REG FILE

NRC PDR

I & E (2)

MIPC

SCHROEDER/IPPOLITO

HOUSTON

NOVAK/CHECK

GRIMES

CASE

BUTLER

HANAUER

TEDESCO/MACCARY

EISENHUT

BAER

SHAO

VOLLMER/PUNCH

KREGER/J..COLLINS

EXTERNAL DISTRIBUTION

CONTROL NUMBER

LPDR: Athens, Ala

TIC:

NSIC:

11579
004

100

100

100

100 100 100 100 100 100 100 100 100 100
100 100 100 100 100 100 100 100 100 100
.....

100 100 100 100 100 100 100 100 100 100

100 100 100 100 100 100 100 100 100 100

100

100



TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

November 10, 1976

Regulatory Docket File



Mr. Norman C. Moseley, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
230 Peachtree Street, NW., 8th Floor
Atlanta, Georgia 30303


Dear Mr. Moseley:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 -
DOCKET NO. 50-260 - FACILITY OPERATING LICENSE DPR-52 - REPORTABLE
OCCURRENCE REPORT BFRO-50-260/7614

The enclosed report is to provide details concerning control room annunciator 2-XA-55-8E that failed. This report is submitted in accordance with Browns Ferry Technical Specifications Section 6. This event occurred on Browns Ferry Nuclear Plant unit 2.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



H. S. Fox
Director of Power Production

Enclosure (3)
CC (Enclosure):
Director (3)

Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

1942


1942



1942

1942

1942



1942

1942

1942

1942

LICENSEE EVENT REPORT

CONTROL BLOCK:

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME														LICENSE NUMBER														LICENSE TYPE										EVENT TYPE																				
01	A	L	B	R	F	2									0	0	-	0	0	0	0	-	0	0					4	1	1	1	1					0	3																			
						14									15											25											26											30					31					32

CATEGORY										REPORT TYPE										REPORT SOURCE										DOCKET NUMBER														EVENT DATE										REPORT DATE																																																							
01	CON-1										L	L										0										5	0										-	0										2	6										0	1										0	1										2	7										6											
										57											58											59											60											61											68											69											74											75											80

EVENT DESCRIPTION

02	Control room annunciator 2-XA-55-8E failed. This annunciator is for smoke and heat																																																																																80
03	alarms in the fire protection system.																																																																																80
04																																																																																	80
05																																																																																	80
06																																																																																	80

SYSTEM CODE										CAUSE CODE										COMPONENT CODE										PRIME COMPONENT SUPPLIER										COMPONENT MANUFACTURER										VIOLATION																																					
02	A	B									E											A	N	N	U	N					L											L	2	9	5					N																																					
										9											11											12											17											43											44											47											48

CAUSE DESCRIPTION

03	The power supply card failed, Lundell Controls part number 310948 in the Statalarm																																																																																80
04	annunciator. (BFRO-50-260/7614)																																																																																80
05																																																																																	80

FACILITY STATUS										% POWER										OTHER STATUS										METHOD OF DISCOVERY										DISCOVERY DESCRIPTION															
11	B									0	5	9									N/A										A											N/A													
										9											10	11	12									44	45											46											80

FORM OF ACTIVITY RELEASED										CONTENT OF RELEASE										AMOUNT OF ACTIVITY										LOCATION OF RELEASE													
12	2									2											N/A										N/A												
										9											10	11									44	45											80

PERSONNEL EXPOSURES

NUMBER										TYPE										DESCRIPTION											
13	0	0	0								2											N/A									
										9											11	12									80

PERSONNEL INJURIES

NUMBER										DESCRIPTION																					
14	0	0	0								N/A																				
										9											11	12									80

OFFSITE CONSEQUENCES

15	N/A																																																																																80
----	-----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE										DESCRIPTION																				
16	2									N/A																				
										9											10									80

PUBLICITY

17	N/A																																																																																80
----	-----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	Replaced power supply card and returned annunciator to normal																																																																																80
19																																																																																	80

NAME: _____ PHONE: _____

