



Consumers  
Power  
Company

General Offices: 212 West Michigan Avenue, Jackson, Michigan 49201 • (517) 788-0550

February 19, 1981


Mr James G Keppler  
Office of Inspection and Enforcement  
Region III  
U S Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60127

DOCKET 50-255 - DPR-20 - PALISADES PLANT -  
LICENSEE EVENT REPORT 81-007 - INOPERABLE  
AUXILIARY FEEDWATER PUMP

On the reverse side is LER 81-007 which is reportable under Technical Specifications 6.9.2B(2).

Steven R Frost  
Palisades Licensing Engineer

CC Director, Office of Nuclear Reactor Regulation  
Director, Office of Inspection and Enforcement  
NRC Resident Inspector



A002  
s  
1/1

FEB 23 1981

LICENSEE EVENT REPORT

CONTROL BLOCK: <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>										(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)									
01 MIPAL1										200-000000-000341111145									
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80										L605000255701228180219819									
CON'T										REPORT SOURCE									
01										L605000255701228180219819									
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)																			
02 During operator rounds it was discovered that the overspeed trip device																			
03 for the turbine-driven auxiliary feedwater pump was in the tripped																			
04 condition. The overspeed trip was immediately reset, thereby restoring																			
05 the pump to operable status. Condition is believed to have existed for																			
06 approx. one hour prior to discovery. LER 81-05 reported a similar																			
07 occurrence. Event reportable per TS 3.5.2 and 6.9.2.B2.																			
08																			
09																			
SYSTEM CODE										CAUSE CODE									
H H (11)										A (12)									
CAUSE SUBCODE										COMPONENT CODE									
F (13)										TURBINE (14)									
COMP. SUBCODE										VALVE SUBCODE									
Z (15)										Z (16)									
LER/RO REPORT NUMBER										EVENT YEAR									
17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80										81									
ACTION TAKEN										FUTURE ACTION									
X (18)										X (19)									
EFFECT ON PLANT										SHUTDOWN METHOD									
Z (20)										Z (21)									
HOURS										ATTACHMENT SUBMITTED									
000000 (22)										N (23)									
NPRD-4 FORM SUB.										PRIME COMP. SUPPLIER									
N (24)										A (25)									
REVISION NO.										COMPONENT MANUFACTURER									
0 (32)										W315 (26)									
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)																			
10 Approx. one hour prior to discovery of the condition, contractor workers																			
11 had been observed moving gas bottles into the aux. FW pump room.																			
12 A worker apparently accidentally bumped the overspeed trip. To prevent																			
13 recurrence, indoctrination training for contractor workers is being revised																			
14 to stress necessity to exercise caution when working in vital areas.																			
FACILITY STATUS										METHOD OF DISCOVERY									
E (28)										A (31)									
DISCOVERY DESCRIPTION (32)																			
Operator Observation																			
ACTIVITY CONTENT										DISCOVERY DESCRIPTION (32)									
RELEASED OF RELEASE																			
Z (33)																			
PERSONNEL EXPOSURES										DISCOVERY DESCRIPTION (32)									
NUMBER																			
0000 (37)																			
PERSONNEL INJURIES										DISCOVERY DESCRIPTION (32)									
NUMBER																			
0000 (40)																			
LOSS OF OR DAMAGE TO FACILITY										DISCOVERY DESCRIPTION (32)									
TYPE																			
Z (42)																			
PUBLICATION										DISCOVERY DESCRIPTION (32)									
ISSUED																			
N (44)																			
NRC USE ONLY																			