

OP 590 - Elevated Work Platforms



CABRERA SERVICES
RADIOLOGICAL · ENGINEERING · REMEDIATION

EWP Inspection Form

EWP Operator must inspect/document equipment daily, using this form.

Project Name:

Project Number:

Date: 3-22-17

Operator:

Make/Model:

Inspection

EWP Inspection

General appearance (hood, paint, undercarriage)

Satisfactory ☒

Unsatisfactory ☐

N/A ☐

Tires (adequate tread)

Satisfactory ☒

Unsatisfactory ☐

N/A ☐

Batteries (tie-downs in place, corroded, leaking)

Satisfactory ☒

Unsatisfactory ☐

N/A ☐

Hydraulic Oil Levels

Satisfactory ☐

Unsatisfactory ☐

N/A ☒

Engine Oil Levels

Satisfactory ☐

Unsatisfactory ☐

N/A ☒

Coolant Levels

Satisfactory ☐

Unsatisfactory ☐

N/A ☒

Structural Arms (welds and paint condition)

Satisfactory ☒

Unsatisfactory ☐

N/A ☐

Chain properly lubricated

Satisfactory ☐

Unsatisfactory ☐

N/A ☒

Outriggers deployed and stable

Satisfactory ☐

Unsatisfactory ☐

N/A ☐

Basket in sound condition (toe boards, flooring)

Satisfactory ☐

Unsatisfactory ☐

N/A ☒

Guardrails intact, swing gate functional

Satisfactory ☒

Unsatisfactory ☐

N/A ☐

Controls properly marked/labelled and functional

Satisfactory ☒

Unsatisfactory ☐

N/A ☐

Ground controls (emergency override) functional

Satisfactory ☒

Unsatisfactory ☐

N/A ☐

Motion Alarm functional

Satisfactory ☒

Unsatisfactory ☐

N/A ☐

Fire Extinguisher (min 5 lbs B:C)

Satisfactory ☒

Unsatisfactory ☐

N/A ☐

Operators manual present

Satisfactory ☒

Unsatisfactory ☐

N/A ☐

Utilities

Safe distance from overhead lines (min 10 feet)

Satisfactory ☒

Unsatisfactory ☐

N/A ☐

Work Area

Work zone demarcated and barriers erected

Satisfactory ☒

Unsatisfactory ☐

N/A ☐

Non-essential personnel behind barriers

Satisfactory ☒

Unsatisfactory ☐

N/A ☐

Area clear of obstructions, holes, uneven surfaces

Satisfactory ☒

Unsatisfactory ☐

N/A ☐

Travel routes clear and demarcated

Satisfactory ☒

Unsatisfactory ☐

N/A ☐

Overhead obstructions marked

Satisfactory ☒

Unsatisfactory ☐

N/A ☐

Personal Protective Equipment

Fall protection (harness and lanyard) available and in use

Satisfactory ☒

Unsatisfactory ☐

N/A ☐

Anchorage points intact

Satisfactory ☒

Unsatisfactory ☐

N/A ☐

Comments: