

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

0 1 G A E I 2 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

CONT

0 1 REPORT SOURCE L 0 5 0 0 0 3 6 6 7 0 8 0 9 7 9 8 0 8 1 6 7 9 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 The Lock on the Radwaste Shield Plug hoist control switch was found broken off. This

0 3 would allow free access to the Radwaste Drum Isles without the key.

0 3 Would allow free access to the Radwaste Drum Isles without the key.

04 _____

05 _____

06 _____

0	7	
---	---	--

08 _____ 80

7	8	9	SYSTEM CODE		CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE				COMP. SUBCODE	VALVE SUBCODE				
0	9		X	X	X	Z	Z	Z	Z	Z	Z	Z	Z			
7		8	9	10	11	12	13	14	15	16	17	18	19	20		
LER/RO REPORT NUMBER			EVENT YEAR			SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.				
17			7	9	—	0	6	8	/	0	3	L	—	0		
21	22	23	24	25	26	27	28	29	30	31	32					
ACTION TAKEN		FUTURE ACTION	EFFECT ON PLANT		SHUTDOWN METHOD	HOURS		ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER			
A	A		Z		Z	0	0	0	N	N	N	A	Z	9	9	9
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 A Maintenance Request was initiated to fabricate a metal box with a locking device to

prevent operation of the hoist without the key being checked out. Work was completed

1 2 on August 10, 1979. During the time the lock was off of the control switch the shield

1 3 plugs were under constant surveillance by Ga. Power Security to prevent unauthorized

entry into the Radwaste Building.

7	8	9											80				
FACILITY STATUS			% POWER				OTHER STATUS				METHOD OF DISCOVERY		DISCOVERY DESCRIPTION				80
1	5	E	0	9	4	NA				A	Operator Observation				80		
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	

ACTIVITY CONTENT
RELEASED OF RELEASE

1	6	2	33	2	34
7	8	9	10	11	

AMOUNT OF ACTIVITY (35)
NA

LOCATION OF RELEASE (36)
NA

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	37	Z	38	NA	39

PERSONNEL INJURIES									
NUMBER			DESCRIPTION						
1	2	3	4	5	6	7	8	9	10
0	0	0	40	NA					

7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30	
LOSS OF OR DAMAGE TO FACILITY																																															
TYPE DESCRIPTION																																															
NA																																															
79082 40528																																															

PUBLICITY
 ISSUED: NA DESCRIPTION: NA
 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20
 68 69 70

POOR ORIGINAL

783-048

912 - 367-6694