



**Florida
Power**
CORPORATION

24 July 1979
3-0-3-a-2
CS-79-215

USNRC
JUL 26 4 9:03

Mr. J. P. O'Reilly, Director
Office of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
101 Marietta St., Suite 3100
Atlanta, GA 30303

Docket No. 50-302
License No. DPR-72
Ref: RII: TJMcH
50-302/79-13

Dear Mr. O'Reilly:

We offer the following supplemental information to the "B" apparent Item of Noncompliance noted in the referenced inspection report.

Further investigation of this matter has revealed that during the time period of 17 to 19 April 1979, the Reactor Building sump inventory and discharge were not monitored for a period of about thirty-five (35) hours, as stated in the Notice of Violation. Documented data does not uphold our contention that all sump inventory indicators were "off scale high".

In order to prevent recurrence of this violation we have:

- Revised SP-300, to require, a) wide and narrow range logging of the Reactor sump level each shift, and b) logging of Reactor Building sump narrow range recorder level each shift.

The implementation of this revision will be effective by 1 August 1979 and full compliance will be achieved.

If there are further questions, please contact us.

Very truly yours,

W. P. Stewart
Manager, Nuclear Operations

Nuclear Plant Manager

JC/rc

852 083

7908300 080

790457